

H. B. Carr

Burlington

January 27, 1969

E. L. Kanyok


Burlington

J. C. Fisher
File ✓

Reliable 2 Roll Mill

Per your request regarding the lowering of the RPM on the 2 roll mill at Burlington, the Maintenance foreman suggested that a job ticket be submitted to remove the gear safety shield so he can check the possibility of changing the gear ratio to lower the RPM.

As soon as this is accomplished, you will be informed of the possibility and approximate cost of this change.


E. L. Kanyok

ELK/rjl