

MONSANTO CHEMICAL COMPANY

Location: Texas City, Texas

Date : August 15, 1961

Subject : Minutes of the Plant Manager's Safety Board
August 14, 1961

Those Present:

E. H. Jones
J. M. Chamberlin
N. F. Wood
J. E. Fox
W. F. Zimmermann
A. J. Romeril
C. L. Gilmore
R. L. Browning
J. G. McQuarrie
H. M. Keating
W. R. Nisbet
G. T. Ryan
R. V. Butz for W. H. Slager
W. R. Robirds for G. D. Rucker
F. E. Grissom (Visitor)
J. W. Kongable (Visitor)

OLD BUSINESS

1. Supervisor Safety Training

This training will begin on September 5, and the schedules have been issued. Schedules for instructors will be prepared and mailed to them.

2. Plant Safety Index

The committee submitted their proposal and after considerable discussion, it was decided to do the following:

- A. Revise Bulletin P-0111, Major Incident Investigation.
- B. Make preparation for using the Index during 1962 on a trial basis.
- C. Report the Index values on a monthly basis to the General Operating Supervisors only.

SC

16894

LAM024164

NEW BUSINESS1. Hourly Safety Committee

The items will be handled by the Safety Director.

2. Pipe Rack Signs

After a lengthy discussion of Mr. Fox's letter and the problem of maintaining the accuracy of the pipe rack signs, it was decided that:

- A. Pipe rack drawings should be brought up-to-date for those locations where signs exist.
- B. Each General Operating Supervisor will provide a knowledgeable man to work on a team to bring the signs up-to-date.
- C. This team will report to Mr. Nisbet for instructions.

3. Home Safety Review Magazine

It was agreed that this magazine was of value in our Off-The-Job Safety Program, and Mr. Chamberlin will discuss with the Safety Director the matter of whether or not it can be included in the budget for 1962.

4. Eye Baths and Showers

It was agreed that no plant-wide change should be made, but that the existing eye baths should be brought up to the existing standard, or alternate standard, and all of the "garage type" hose valves should be removed where they now exist on eye baths. It was further suggested that a plastic or rubber pad with the circle on it should be considered for marking the location of safety showers. It is believed that the circle which is specified in the standard is a good marking, but it is quite expensive when put on by paint which is now the case.

MISCELLANEOUS

Mr. Gilmore again asked for the status report on the Process Hazard Committee items.

Mr. Gilmore read a letter from one of the employees' wives concerning self protection training for shift workers' wives. This will be discussed at the next meeting.



C. L. Gilmore

SC

16895