

R968460 - R.F.G. PERSONNEL MONITOR - PERSONAL DATA
 01/01/80 TO 12/31/80 DATE 02/17/81 TIME 141721 PAGE 1

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	F/T	PPM	PUMP POS	BRK TH	RESP
HENRY	731	000	010	A	011280	360	.46	OUT MASK	NO	2
HENRY	731	000	010	A	022380	360	5.04	OUT MASK	NO	2
HENRY	731	000	010	A	032380	360	.06	OUT MASK	NO	2
HENRY	731	000	010	A	102680	360	5.48	OUT MASK	>20%	2

NGC 08106

R96846C - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
 01/01/79 TO 12/31/79 DATE 03/27/80 TIME 115946 PAGE 1

PLANT NAME.....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP
HENRY	731	000	010	A	011179	360	16.32	OUT MASK	NO	2
HENRY	731	040	010	A	012079	015	1.24	OUT MASK	NO	2
HENRY	731	000	010	A	012979	360	2.84	OUT MASK	NO	2
HENRY	731	C0C	C1C	A	031279	360	4.48	OUT MASK	NC	2
HENRY	731	000	010	A	040579	360	1.52	OUT MASK	NO	2
HENRY	731	000	010	A	051279	360	1.10	OUT MASK	>20%	2
HENRY	731	C0C	010	A	060179	360	1.59	OUT MASK	NO	2
HENRY	731	C00	010	A	070279	360	2.43	OUT MASK	NO	2
HENRY	731	000	010	A	080379	360	9.37	OUT MASK	NO	2
HENRY	731	C00	010	A	090879	360	1.89	OUT MASK	NO	2
HENRY	731	000	010	A	101879	360	.07	OUT MASK	NO	2
HENRY	731	047	010	A	102879	015	.13	OUT MASK	NO	2
HENRY	731	C00	010	A	111579	360	.29	OUT MASK	NO	2
HENRY	731	C0C	010	A	121479	360	.88	OUT MASK	NC	2

NGC 08107

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
 01/01/78 TO 12/31/78 DATE 01/18/79 TIME 080117 PAGE 1

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP
HENRY	731	000	010	A	011278	360	.47	OUT MASK	NO	2
HENRY	731	000	010	A	022778	360	.14	OUT MASK	NO	0
HENRY	731	000	010	A	032178	360	.77	OUT MASK	NO	2
HENRY	731	000	010	A	040678	360	.89	OUT MASK	NO	0
HENRY	731	000	010	A	050578	360	.58	OUT MASK	NO	2
HENRY	731	000	010	A	060278	360	.27	OUT MASK	NO	2
HENRY	731	000	010	A	071978	360	4.85	OUT MASK	NO	2
HENRY	731	000	010	A	080178	360	.05	OUT MASK	NO	2
HENRY	731	000	010	A	091478	360	6.20	OUT MASK	NO	0
HENRY	731	000	010	A	092578	360	.35	OUT MASK	NO	2
HENRY	731	000	010	A	101878	360	.26	OUT MASK	NO	2
HENRY	731	000	010	A	111578	360	.72	OUT MASK	NO	2
HENRY	731	000	010	A	120778	360	2.22	OUT MASK	NO	2

NGC 08108

R96846C - B.F.C. PERSONNEL MONITOR - PERSONAL DATA
 01/01/77 TO 04/30/78 DATE 05/08/78 TIME 144453 PAGE 1

PLANT NAME.....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP
HENRY	731	000	009	A	052277	360	5.72	OUT MASK	>20%	2
HENRY	731	000	009	A	060477	360	.34	OUT MASK	NC	2
HENRY	731	000	009	A	071077	360	1.22	OUT MASK	>20%	2
HENRY	731	000	009	A	081577	360	.30	OUT MASK	>20%	0
HENRY	731	000	009	A	091377	360	.01	OUT MASK	>20%	0
HENRY	731	000	009	A	101277	360	.09	OUT MASK	NC	2
HENRY	731	000	009	A	111677	360	.00	OUT MASK	NC	2
HENRY	731	000	010	A	120777	360	.23	OUT MASK	>20%	2
HENRY	731	040	010	A	121977	015	.16	OUT MASK	NC	2
HENRY	731	014	009	A	122777	015	15.89	OUT MASK	NC	2
HENRY	731	014	010	A	122877	015	2.06	OUT MASK	NC	2
HENRY	731	000	010	A	011278	360	.47	OUT MASK	NC	2
HENRY	731	000	010	A	022778	360	.14	OUT MASK	NC	0
HENRY	731	000	010	A	032178	360	.77	OUT MASK	NC	2
HENRY	731	000	010	A	040678	360	.89	OUT MASK	NC	0

NGC 08109

WE CHEMICAL M1

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH RS
HENRY	731	000	011	A	011476	360	2.50		
HENRY	731	000	028	D	032676	360	4.80		
HENRY	731	000	028	D	040576	360	.34		
HENRY	731	016	009	A	051376	015	.00		
HENRY	731	000	009	A	070876	342	.37		

NGC 08110

DISTRIBUTION ATTENTION M.I.S. DEPARTMENT

R96846

VCM MONITORING - PERSONAL RECORD

DATE 01/15/76

FROM 01/01/75 TO 12/31/75

PLANT NAME	SPL.PERIOD	AREA	TASK	JOB	SHIFT	DATE	EXPD.TIME	PM-VCM	R
HENRY	LONG	732	000	016	D	042375	240	0.03	0
HENRY	LONG	732	000	016	D	050875	360	0.23	0
HENRY	LONG	731	000	011	A	061375	360	0.28	2
HENRY	LONG	731	000	011	A	072375	360	0.31	2
HENRY	LONG	731	000	011	A	082075	360	0.37	0
HENRY	LONG	731	000	011	A	092575	360	0.84	0
HENRY	LONG	731	000	011	A	102575	360	1.20	0
HENRY	LONG	731	000	011	A	112975	360	3.10	0
HENRY	LONG	731	000	011	A	121175	360	1.30	0
HENRY	SHORT	731	001	017	A	061575	90	8.50	2

NGC 08111