

LEAK DETECTION REPORTING FORM

ABERDEEN PVC PLANT

1. Honeywell Chromatograph No.	# 1
2. Date	12-11-77
3. Time	1100
4. Monitoring Point With High Readings	6
5. Readings, PRM	10 9 10 10
6. Operator Action Result	Got Hops to Check out Area, Found Socket on Bottom of 5.0 on Steam-tank Tank Leaking. Called Maintn room to replace socket.
7. Shift Supervisor Action Result	Replaced socket
8. Maintenance Action Result	Replaced steam-tank
9. Verified By	
10. Operator	Jerry Eastman
Shift Supervisor	Bobby Thompson