

Niel Hooker

1/13/79



ASBESTOS MILL BOARD.

1. Fibers are released when processed in our shops.
 - Substitute material
 - Purchase the gaskets. Bore in our work shop, use that as gaskets in the plant.

Define a lead time when it will be done.

2. Other gaskets. - substitute material due being developed.
Specification of gaskets - Pressure & temperature requirements - Then we can find substitutes.

HH Jensen FPGD Sigs

Bob Lawrence Engg Cont.

WE Longfield Engg Design

Joe Baumgartner Engg Design → 1/18/79 - called, gave address, Mike

WE Live Say FPGD Component Engg