

5. The worker proceeds to equipment room and removes all clothing except respiratory protection equipment. Extra work clothing may be stored in contaminated end of the unit. Disposable coveralls are placed in a bag for disposal with other material. The worker then proceeds rapidly into the shower room. Respiratory protection equipment should be removed last to prevent inhalation of fibers during removal of contaminated clothing.

6. After showering, the worker moves to the clean room and dresses in either new coveralls for another entry or street clothes if leaving.

7. Respirators are picked up, cleaned and wrapped by protected workers in a separate area by washing. The respirators are

~~then brought to the clean room by an outside worker.~~ The cleaners then exit through the shower units as usual.