

FILE NAME: Colonial Sugar Refinery (CSR)

DATE: 1950 Feb 22

DOC#: CSR158

DOCUMENT DESCRIPTION: Govt Inspection Report Noting Bad
Conditions at Wittenoom Gorge

Copy of report on Mines File 1301/47

Copy of report sent to Inspector Boyland.

GOVERNMENT OF WESTERN AUSTRALIA.

Mines Department, Marble Bar.

22nd February, 1950.

The District Inspector Boyland,
Mines Department,
CUE.

Re Wittenoom Gorge.

I beg to acknowledge therewith of your memo. of the 14th Feb. together with your report on the conditions as you found them at Wittenoom Gorge.

Do you think it would warrant the appointment of a Ventilation Officer to make them realize that their ventilation is going to be one of their big problems before very long.

Would it be possible for you to get the Department to supply me with a Thermometer I think that the time has come now that it is most essential. (Wittenoom getting further in and the Blue Spots C.M. getting deeper.)

I found things generally to be in very bad condition at the Gorge and this was my report.

The men working on the surface have no proper crib place

Request that a crib place be made available for the men working on the surface. (the men were eating more dust than food)

Ventilation nothing had been done to improve things since your visit. At two working faces the Venturals were reasonably placed but six others were from twenty seven feet to fifty feet back from the faces (properly measured) Also requested that a start be made immediately to bring them all up to within 25 feet of the working faces.

Electrical System underground I was wised up by some very competent electricians of the appalling state of affairs that existed in the wiring underground, and no earthing etc. I have had several reports of men being knocked while handling their Leads at the faces. Also requested that this matter be dealt with at once.

PLAINTIFF'S
EXHIBIT

102630