

1992 ANNUAL VCM SURVEY

LEAK	PPM	LOCATION
001OM	500	Bleeder valve on pipe rack in front of VCM recievers.
002OM	400	Pressure gage on south seal water separator.
003OM	60	Valve on south seal water separator.
OO4TF	450	Bleeder valve on north transfer pump in VCM tank farm (Valve #34).