
2022 Facility Aerial – Google Earth – Depictions not to scale



Beverly Port Marina – EPA Inspection 8/20/2024

08/20/2024
EPA Inspection

Beverly Port Marina


43 Water Street
Beverly, MA


Damian Bednarz

Margarita Chatterton

Joe Canzano

Brochure for double wall containment fuel piping (for under dock)





Facility's documentation of observed sheen (unclear photo)

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



4,000 gal double walled gasoline tank

8,000 gal double walled tank (4,000 gasoline and 4,000 diesel)

ED_019088A_00004069-00003

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano





EPA

Emergency fuel shut off to dock and dispensers, accessible by removing grate

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



(3) Fuel lines running underneath dock to dispensers. Labeled fuel types. Additional shut off valve access

08/20/2024
EPA Inspection


Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Tags labelling pipe segments for leak inspections and documentation

ED_019088A_00004069-00008

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



ED_019088A_00004069-00010

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA



Spill kit in shed near dispensers



Outfall 003

Town of Beverly
Outfall Pipe

EPA





EPA



CB3-1

08/20/2024
EPA Inspection

Beverly Port Marina


43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano






CB1-1 – Discharges to Outfall 001



Outfall 001- Substantially Identical to Outfall 002



Outfall 002 – Substantially Identical to Outfall 001

EPA





Rust staining and discoloration in Outfall 002 drainage area

ED_019088A_00004069-00021

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Eastern Storage Yard, outfall 001 and outfall 002 drainage areas

ED_019088A_00004069-00023

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Out of commission Marina Travel Lift and Oil Receptacles in Outfall 001 Drainage Area

EPA



Uncovered waste (overflow) behind dumpster

Uncovered dumpster and pavement staining in Outfall 002 Drainage Area

ED_019088A_00004069-00025

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



55 gallon oil drum without secondary containment

ED_019088A_00004069-00027

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Engine Test Tank, Approximately 300 gallons. Water contained considered process wastewater. Dispose of properly.

EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Indirect Fired Heater, operated from diesel #1 or #2, 33 gallon fuel tank. Not applicable to total SPCC Plan Oil Capacity

EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



250 gallon oil storage tank, single walled, no secondary containment. Tank to be removed.

EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Post Inspection 8/21/2024: 250 gallon oil storage tank, single wall, set to be removed

EPA

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Drain in Service Building of unknown utility/flow. 250 gallon single walled waste oil tank located in the same room

EPA

08/20/2024
EPA Inspection


Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz

Margarita Chatterton

Joe Canzano



Paint Chips from recent paint job on side of Service Building on pavement

EPA



Operator explains fuel piping replaced when corrosion is evident, however, the inside of the pipe often does not feature the same extent of corrosion

EPA





CB4-1 – Outside of Boat Storage Building



CB4-2 – Outside of Boat Storage Building





EPA

ED_019088A_00004069-00039


Pressure wash pad, washwater collection point, and berming
Pressure wash sump


Pressure wash pad, sump, and collection system
Boat Storage Building
005
006


Pressure wash sump

08/20/2024
EPA Inspection

Beverly Port Marina

43 Water Street
Beverly, MA

Damian Bednarz


Margarita Chatterton

Joe Canzano



Damaged portion of berm


ED_019088A_00004069-00041



CB5-1


EPA

ED_019088A_00004069-00042


Pressure wash pad, sump, and collection system
Boat Storage Building
005
006



Outfall 005


Outfall 005




Pressure wash water filtration and settling tanks

EPA



CB6-2

ED_019088A_00004069-00045


Pressure wash pad, sump, and collection system
Boat Storage Building
005
006

Outfall 006