



Safety & Training News

Pascagoula Refiner.


May 19, 1960

DO THE JOB RIGHT - AND IT WILL BE DONE SAFELY

The following is a safety rule reminder:

The following procedure will be followed when removing old line and vessel insulation. Line and vessel insulation installed prior to 1972 may contain asbestos. Please follow all safety precautions described:

1. Before removing insulation, all insulating materials should be wet down.
2. Pick up and bag all asbestos scrap as soon as it is removed.
3. Loose asbestos that collects on the ground should be wetted and cleaned up as soon as possible.
4. Only special plastic bags with the appropriate asbestos warning label are to be used. They are available in the storehouse.
5. The bags containing asbestos wastes should be set aside for disposal by an approved hauler.
6. Employees removing the insulation will wear a 3M 8710 single-use throwaway respirator and paper-type coveralls. The respirators are available from the storehouse. The coveralls are available from the storehouse. After use, the respirators and coveralls should be discarded in the plastic bags.


Charles C. Albritton
Safety Engineer

PLAINTIFF'S EXHIBIT

B&R-389