

NAPA RAYLOC
INTER PLANT
P. O. S. COMMUNICATION

Procedure
Or
Specification

POS COMMUNICATION NO.: CD-88-4

DATED: September 7, 1988

FROM: PAUL L. LECOUR
TO: ALL RAYLOC PLANTS
STATUS: PERMANENT UNTIL FURTHER NOTICE
PRODUCT: CLUTCH DISCS
SUBJECT: ASBESTOS CAUTION STATEMENT

Well, the time has come that we must start identifying all products that contain asbestos fibers. Currently, this will involve our brake shoes, disc assemblies and clutch assemblies that we produce, purchase or rebox.

In order to accomplish this task, Joe White has had some stamps made up for this project. Each General Manager was given one of these at the annual Managers' Meeting in Atlanta. The "caution" statement should be placed at a 60 degree angle to the product's identification label that is on the boxed item, preferably on the top of the box. Joe Benator has these stamps.

The statement reads as follows:

CAUTION: Contains asbestos fibers. Avoid creating dust. Breathing asbestos dust may cause lung disease.

The implementation of this POS is immediately. We will be making some labels that will fit all product line boxes. In the meantime, please use your stamps.

Paul L. LeCour

PLL:jw

SCF-NAPA-2615

NAPA 032

NOVO110409

