



PROPOSED HANDLING PROCEDURE FOR ASBESTOS GASKETS AND PACKING

STORAGE FACILITY

Preformed gaskets and packing will be stored in a clean storage area. The storage area will be cleaned regularly with a HEPA filter vacuum to prevent accumulation of debris.

INSTALLATION AND REMOVAL OF GASKETS AND PACKING CONTAINING ASBESTOS

If the gasket or packing to be removed is not adhered to the seating surfaces and can be removed by hand, remove and dispose of properly. If the gasket or packing is adhered to the seating surfaces so that mechanical means are used (~~scrapers, sanders, etc.~~) and this operation creates particles in the air or surrounding area, then as a minimum, the asbestos abatement procedure for small scale short duration jobs shall be used.

Glove bag use

1/10/87

ST0408599

ST0408599