



BROWN INSULATING SYSTEMS, INC.

P. O. BOX 33015 11941 ABBEY ROAD NORTH ROYALTON, OHIO 44133 PHONE (216) 237-3444

September 10, 1976

Mr. Francis Bilton
Foseco, Inc.
P O Box 81227
Cleveland, Ohio 44181

Dear Mr. Bilton:


In reviewing your invoices for the Amosite asbestos shipped to our company, there are a few discrepancies as follows:

- 1) Invoice #76-197 shows 31,240# (284 bags) shipped; we received 29040# (264 bags).
- 2) Invoice #76-198 shows 3,300# (30 bags) shipped; receiving only 3,080# (one full pallet - 20 bags and a partial pallet - 8 bags).
- 3) One of these shipments contained seven bags of S11/65 asbestos instead of the S-33/65 Amosite asbestos.

Unfortunately, three bags of the S11/65 asbestos were used and our process came to a screeching halt. We have four bags left which we can not use and are available for return. However, we do feel that we should receive credit for all seven bags since they were not of the S-33/65 Amosite asbestos we agreed to purchase.

Would you please issue corrected invoices showing the above adjustments. Thanking you in advance for taking care of this matter.

Sincerely,



John W. Brown III

JWB:ja



2448