

Form Approved OMB
No. 44-R1387
Approval Expires:
July 30, 1972

U.S. DEPARTMENT OF LABOR

Form No. OSHA-20
May, 1971

MATERIAL SAFETY DATA SHEET

SECTION I						
MANUFACTURER'S NAME MONSANTO COMPANY			EMERGENCY TELEPHONE NO. (314) 694-1000			
ADDRESS, Number, Street, City, State, and ZIP Code 500 North Lindbergh Boulevard, St. Louis, Missouri 63166						
CHEMICAL NAME AND SYNONYMS Mixture			TRADE NAME AND SYNONYMS Aroclor 1254 (A13B1)			
FORMULA Chlorinated aromatic			FORMULA Mixture			
SECTION II HAZARDOUS INGREDIENTS						
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)	
PIGMENTS			BASE METAL			
CATALYST			ALLOYS			
VEHICLE			METALLIC COATINGS			
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX			
ADDITIVES			OTHERS			
OTHERS						
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)	
SECTION III PHYSICAL DATA						
BOILING POINT (°F.)		760 mm	365-400°C	SPECIFIC GRAVITY (H ₂ O = 1) (25/25°C)		1.538
VAPOR PRESSURE (mm Hg.)		180-220°C	3 mm	PERCENT VOLATILE BY VOLUME (%)		N.A.
VAPOR DENSITY (AIR = 1)				EVAPORATION RATE (BuAc = 1)		<1
SOLUBILITY IN WATER		20°C negligible	<0.01%			
APPEARANCE AND ODOR		Yellow viscous oil		aromatic odor		
SECTION IV FIRE AND EXPLOSION HAZARD DATA						
FLASH POINT (Method used)		None		FLAMMABLE LIMITS		
				Lol		Uol
				N.A.		N.A.
EXTINGUISHING MEDIA						
SPECIAL FIRE FIGHTING PROCEDURES						
Respiratory protection when fighting fires where exposure to vapors or gases is possible.						
ADDITIONAL FIRE AND EXPLOSION HAZARDS						
Highly toxic gases (chlorides and chlorine) can be evolved in fires of this product.						

DSW 267244

STLCOPCB4062657

THRESHOLD LIMIT VALUE	0.5 mg/m ³ of air
EFFECTS OF OVEREXPOSURE Skin irritation in the form of chloracne, systematic intoxication leads to nausea, vomiting, loss of weight, edema and abdominal pain.	
EMERGENCY AND FIRST AID PROCEDURES Remove from exposure. Remove contaminated clothing. Wash contacted area with large amounts of water and soap. Refer to physician.	

SECTION VI REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	
INCOMPATIBILITY (Materials to avoid)			
HAZARDOUS DECOMPOSITION PRODUCTS CO, CO ₂ , smoke, soot, chlorides and chlorine			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Absorb on clay, sawdust or other absorbant material. Place in drums. Bury in approved chemical landfill in accordance with local and state regulations.	
WASTE DISPOSAL METHOD Burn in an approved incinerator in accordance with local and state regulations.	

SECTION VIII SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type) Bureau of Mines approved respirator for organic vapors.			
VENTILATION	LOCAL EXHAUST	Yes - for vapors	SPECIAL
	MECHANICAL (General)		OTHER
PROTECTIVE GLOVES Rubber		EYE PROTECTION Chemical goggles	
OTHER PROTECTIVE EQUIPMENT			

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE Avoid skin and eye contact, avoid inhalation of vapors	
OTHER PRECAUTIONS	

DSW 267245

While the information and recommendations set forth herein are believed to be accurate as of the date hereof, MONSANTO COMPANY MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON.

JAG:HOH:JTG:WBP

1/25/72

STLCOPCB4062658