

**COMPANY SANITIZED – Does not contain TSCA Confidential  
Business Information (CBI)**

**DAIKIN**

AR 226 - 3730

AR-226

**COMPANY SANITIZED**

**DAIKIN AMERICA, INC.**

905 State Docks Road (35601)  
P.O. Box 2252  
Decatur, AL 35609  
Tel.: 256-306-5000  
Fax: 256-306-5599

2006 NOV -1 PM 1:06

RECEIVED  
OPPT/CBIC

October 30, 2006



Ms. Mary F. Dominiak  
U.S. Environmental Protection Agency  
EPA East, Mail Code 7405M  
1200 Pennsylvania Avenue, NW  
Washington, DC 20460

**Subject: 2005 Material Balance for Daikin America, Inc. Decatur Plant  
(TSCA CBI)**

Dear Ms. Dominiak:

This report is submitted pursuant to the APFO Users Letter of Intent (LOI) dated March 14, 2003. In this report, the Perfluorooctanoic Acid (PFOA) (CASN 335-67-1) material balance for the Decatur Plant will be presented. A summary comparing 2005 to 2000 material balances is provided.

Decatur Plant Estimated PFOA Mass Balance for 2005

**CBI Redacted**

2006 NOV -1 PM 1:10

RECEIVED  
OPPT/CBIC

**Company Sanitized**

299809

## COMPANY SANITIZED – Does not contain TSCA Confidential Business Information (CBI)

Table 2: 2005 Recycle and material sent to incinerator

| (Pounds/year) |              |
|---------------|--------------|
| Incineration  | CBI Redacted |
| Recycle       |              |

### Comparison of 2000 and 2005 Material Balances

A comparison of 2000 and 2005 data is shown in Table 3 below.

Table 3: Comparison of 2000 and 2005

**CBI Redacted**

If you have any questions, please contact me at 256-306-5600 or e-mail at [roussel@daikin-america.com](mailto:roussel@daikin-america.com).

Sincerely,



Randy Roussel  
Regulatory Affairs Manager

Company Sanitized