

FILE NAME: Marley (MAR)

DATE: 1972 Jan 1

DOC#: MAR029

DOCUMENT DESCRIPTION: Memo

Langlin	nm
Wright	
WW Jones	

1-21-72

Asbestos Dust

Note new regulations with my note attached
This is a health problem & not a nuisance dust
As I see it we should

- Contact your present respirator supplier & see if he can recommend an industrial hygienist to do our testing. (The test equipment is quite expensive. We only know of (2) machines in Ken)
- Test Honeycomb, M-67 & ALB panel fab & assembly areas.
- See that proper respirators are used in areas over 5 fibers/milliliter.
- Before you design & build Proj 5-2353 for Honeycomb scrap disposal, wait until we get new regulations. Note what attached says of asbestos waste & scrap.

Keep us advised as we can be of help in getting this solved. I put a fancy filter on Tannamity saw & we have vents on most saws. We will see what new regulation defines

Bill looked at test equipment at that Eng. Show to trap dust on worker - sampler can then be examined (count of fibers) or sent local for analysis - He is sending scope to Wall. **Lebon**