

N

AREA SAMPLE 00356670

ABERDEEN CHEMICAL PLANT—DOSIMETRY RECORD

No 001086

Name OLD VCM COMPARED - N. COMP. Shift _____ Date 11-14-56

Social Security No. _____ Job Code _____

Instrument No. <u>2566</u>	Start		Stop	
	Time <u>2:45</u>	AM () PM (✓)	<u>4:20</u>	AM (✓) PM ()
Airflow _____				

HAZARD	SAMPLE CONCENTRATION (Time Weighted Average)	Sample Time _____
VCM	<u>10.1</u> - PPM	
Lead	-Micrograms/M ³	PEL: -Micrograms/M ³
Total Dust	-Milligrams/M ³	
		Analyst <u>[Signature]</u>
		Analysis Date <u>11-15-56</u>

Hazard: VCM () Lead () Dust () _____ ()

No 001086

1. I came to work at _____ AM () PM ()

Firewatch Work? Yes / No (Circle One)
--

2. I left work at _____ AM () PM ()

3. I did the regular work of a (enter Job Class) _____

4. I used a respirator during the following jobs (check one)

	None	Dust Mask	Air-Line Resp.	Scott Air-Pak	3 M Air Hat

5. The following unusual events may have caused me to be overexposed:

6. Other comments and information (Use reverse side of card)

Signature _____

Please complete and return to Guard