

In an additional effort to provide stable pallets for shipping, Manville Corporation or related entities utilized an automatic wrapping machine which wrapped a single or double layer of stretch film around the pallet load.

PRODUCT WARNING LABELS

Manville Corporation or related entities placed warning labels on the packaging of its asbestos containing thermal insulation products from which dust might have been released during installation. These labels and dates of their use are as follows:

1964 to 1970

CAUTION

THIS PRODUCT CONTAINS ASBESTOS FIBER.

INHALATION OF ASBESTOS IN EXCESSIVE
QUANTITIES OVER LONG PERIODS OF TIME
MAY BE HARMFUL.

IF DUST IS CREATED WHEN THIS PRODUCT
IS HANDLED, AVOID BREATHING THE DUST.

IF ADEQUATE VENTILATION CONTROL IS NOT
POSSIBLE, WEAR RESPIRATORS APPROVED BY
THE U.S. BUREAU OF MINES FOR PNEUMOCONIOSIS-
PRODUCING DUSTS.

1970 to 1972

CAUTION

THIS PRODUCT CONTAINS ASBESTOS FIBER.
AVOID BREATHING THE DUST. INHALATION
OF ASBESTOS IN EXCESSIVE QUANTITIES
OVER LONG PERIODS OF TIME MAY BE HARMFUL.

IF DUST IS CREATED WHEN THIS PRODUCT
IS HANDLED, USE PROPER PROTECTION.

IF PROPER DUST CONTROL CANNOT BE PROVIDED,
RESPIRATORS APPROVED BY THE U.S. BUREAU OF
MINES FOR PROTECTION AGAINST THE PNEUMOCONIOSIS-
PRODUCING DUSTS SHOULD BE WORN.