

LOT

MAY -0.81 E-1107

OK
A

EST'D WGT 5632

TOTAL EST'D WGT= LBS (CRT ENTRY)

MAKING NOTES

JOB NAME: 01YE698DPS

INSTRUCTIONS				= PRESSING =	RECORD																	
VAT	DATE	TIME	RELEASED BY	PRESS	NO. OF Cakes	PRESS WITH AGITATION	WASH TO 2000 OHMS WITH 35-75 F WATER	TEST AFTER 2 HOURS	LOAD ON 7 CARS	PRESSLOAD	STARTED	CAKES USED	WATER ON	HRS. WASHED	OHMS	HRS. WASHED	OHMS	HRS. WASHED	OHMS	CAKE CONDITION	NO CARS LOADED	EXPLAIN LOSSES
111	11/1	15:43	242	2	92	93	54	54	54	1ST	2ND	3RD	4TH	5TH	9PM	54	12AM				8	

SAMPLES
DELIVER TO

SAMPLED BY
RELEASED BY

= DRYING =
(EXTRUDED) DRY 10 HRS AT 240 DEG F
(NOT EXTRUDED) DRY 10 HRS AT 240 F
LUMP: - OK - WET - SALTS - CONTAMINATED

ADDITIONAL DRYING HOURS REQUIRED

SAMPLES 1 ENV
DELIVER TO COLOR TEST LAB

NO CARS PULLED
SAMPLED BY
RELEASED BY

NO DRUMS
LUMP WGT 5730

= GRINDING =
MILL MIKROATOMIZE SCREEN
MAX. TEMP DEG F
SET ROOF BLAST - GATE AT "9" FOR
HIGH AIR FLOW

RPM SCREEN
MAX. TEMP. F

EXPLAIN LOSSES

SAMPLE WITHOUT MIXING
SAMPLES
DELIVER TO STL

DATE MIXED
SAMPLED BY
RELEASED BY

0.00 *

1107
41
225

3.45 +
0.12 -
3.39 +
0.12 -
3.45 +
0.12 -
3.17 +
0.12 -
3.19 +
0.12 -
3.42 +
0.12 -
3.22 +
0.12 -
3.04 +
0.12 -
3.24 +
0.12 -
3.44 +
0.12 -
3.73 +
0.12 -
3.42 +
0.12 -
3.41 +
0.12 -
3.19 +
0.12 -
3.38 +
0.12 -
3.22 +
0.12 -
3.28 +
0.12 -
2.88 +
0.12 -
57.36 *

18

1