

FILE NAME: Superior Combustion Industries (SCI)

DATE: 1969 Jan 17

DOC#: SCI006

DOCUMENT DESCRIPTION: Field Activity Report

12

OFFICIAL USE ONLY - FEDERAL BUREAU OF INVESTIGATION

1/17/69

FIELD ACTIVITY REPORT

Boilers

Superior Combustion Industries

Frederick and Blackman Street, Wilkes Barre

18701

717-223-0127

Wm. Seiden

Supt.

REPORT: VISUAL, DIRECT, INDIRECT, PRELIM, FOLLOWUP, VISIT

ANALYSIS: ALL INFORMATION REPORTED BY SOURCE

OCCUPATIONAL EXPOSURE	WORKING EXPOSURE	RECOMMENDATIONS		ACCOMPLISHED		
		WRITTEN - VERBAL	YES	NO	IN PROGRESS	
Welding						
Heat						
Noise	70					
Acetylene cutting						
Metal grinding						

ADDITIONAL COMMENTS: TOTAL

OTHERS: YES NO TOTAL

MEDICAL: YES NO

PUNCH CARD YES ☒ NO ☐ FOLDER YES ☒ NO ☐

REMARKS:

Plant Supt. stated he is going to install several ceiling fans and a few wall fans to facilitate the removal of welding fumes. Acetylene cutting is done on large sheets of metal - fumes do not appear to be significant. The work area is a large room with a very high ceiling, but on some occasions when there is an inversion the fumes seem to hang over the work area.

Noise occurs when someone is required to chisel out a defective weld, but this is not a continuous operation. Metal grinding is done frequently. The dust particles are large.

Boilers are placed in a large heating oven to stress release the welded sections. Heat exposure is minimal, welds are x-rayed in a roped off area. A new room will be constructed to house the x-ray operation.

For Action of an Original Record
Please Check
PA STATE ARCHIVES
300 North State, Harrisburg, PA 17120-0039
PA Historical & Museum Commission

J. Memoles

2.0