

MRAY1000-10 RAYLOC ALLIED BRAKE SHOE DRILLED

MATERIAL SAFETY DATA SHEET

Effective Date: March 29, 1993 Code: Allied Brake Shoe Drilled Page: 1

Section 1 - PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NAME: Allied Brake Shoe Drilled
Chemical Name: Cured Segment, Organic

Identity (Edge Code): NRSP11034FF, NSS2200FF, NRSP11033FF, NRSP11032FF,
NRSP11026FE, NSS2215FE, NRSP11035FE, NRST11036FG, NSS2210FG,
NRSP11037FE, NSS2205FE

MANUFACTURER'S NAME:

Allied-Signal Corp.

900 W. Maple Road

Troy, Michigan 48084

EMERGENCY TELEPHONE NO.

(313)362-7196

MISCELLANEOUS INFORMATION:

Formula: Mixture of
Proprietary Ingredients;
See Section 2

SUPPLIER'S NAME:

Rayloc

Division of Genuine Parts Company

600 Rayloc Drive SW

Atlanta, Georgia 30378

REVISION DATE:

May 20, 1997

Section 2 - HAZARDOUS INGREDIENTS

CAS NO.	INGREDIENT	EXPOSURE LIMITS			
		ACGIH	OSHA	VP	
		TLV	PEL	UNITS	MM HG
1332-21-4	Asbestos/Chrysotile	20-50	0.2 Fiber/cc		
1317-65-3	Calcium Carbonate	5-10	5 mg/m3		
7727-43-7	Barium Sulfate	5-20	5 mg/m3		
1344-28-1	Aluminum Oxide	2-5	5 mg/m3		
1309-48-4	Magnesium Oxide	2-5	5 mg/m3		
1333-86-4	Carbon Black	2-5	3.5 mg/m3		
7732-42-5	Graphite	2-5	2.5 mg/m3		
1309-37-1	Iron Oxide	2-5	10 mg/m3		
	Non-hazardous Resins & Fillers	Balance			

.....WARNING.....
AVOID CREATING OR BREATHING DUST. CONTAINS ASBESTOS FIBERS AND OTHER
SUBSTANCES WHICH MAY CAUSE CANCER AND LUNG INJURY.
GENERAL REQUIREMENT: TOTAL DUST SHALL NOT EXCEED 10MG/M3
.....

SCF-NAPA-7095

NAPA 017

NOVO12054

