

POLYMER PRODUCTS DEPARTMENT
MANUFACTURING DIVISION

CC: M. S. DEAK
A. J. PLAYTIS, WASH. WORKS

June 4, 1990

TO: W. P. ANDERSON - WILMINGTON
W. E. CRAWLEY - WASHINGTON WORKS

FROM: H. A. SMITH

Howard Smith
WASHINGTON WORKS C-8 AIR MONITORING
AND PERSONNEL PROTECTION PROGRAM

Ref: 1) HAS to JGL, RDL, WEC - 3/19/90
(This memo contains all the blood data
and air monitoring data for reference)

Ref: 2) HAS to Karrh, et al - 5/31/90
(This memo summarizes the series of C-8
review meetings and the path forward for
the entire C-8 program)

Please proceed with the following:

- 1) Review and update all PERS job descriptions. Modify as needed to include use of "liquid" C-8. Add any new jobs. Don't forget to include fine powder dryer recovery job.
- 2) Review again and emphasize the importance of avoiding C-8 skin contact, use of proper protective equipment, and periodic clean-up of area. (Remember comments from our May 24 tour of the area.)
- 3) Review equipment design and need for modifications. (Per comments from our May 24 tour of the area.)
- 4) Proceed with personnel air monitoring. Start with jobs that now involve handling "liquid" C-8 (previously handled solid C-8); the mechanic's job; the new fine powder dryer recovery job. Data should be reviewed as it is obtained so we can take any corrective action necessary in a timely manner.

As we discussed on May 24, Bill Anderson and I will come to the plant to assist with the PERS review and answer any questions on air monitoring. We should also review items 2 and 3 again.

HAS/is

AJP002168

EID079783