

Asbestos Survey

All asbestos containing material (ACM)
has been removed from this facility.

 Yes
 X No
 Partially Removed

Estimated quantity of asbestos containing material: 264,113 sq. ft.

Condition of material:

	<u>Square Feet</u>
Intact, undamaged	<u> 264,113 </u>
Minor damage (punctures, cuts, exposed ends)	<u> 0 </u>
Moderate damage (broken, cracked sections, crushed wrapping)	<u> 0 </u>
Severe damage (needs immediate attention)	<u> 0 </u>

Estimated quantity of material that is friable: 0

"Friable" refers to material that can be crumbled, pulverized, or
reduced to powder in the hand and can result in the release of
asbestos fibers into the air.

Are plans being made to perform any removal of ACM in the next
12 months?

 Yes X No

We are currently making a survey
to determine the scope and cost
of replacing the asbestos insu-
lation.



Signature T. W. Sands

Vice President & General Mgr.

Southwestern Refining Co., Inc.

Facility

 September 8, 1986
Date

Return to Dennis Johnson (MT-604)

RECEIVED
SEP 10 1986
Medical Services