

*file Crossover Incineration*

J. R. Savage - St. Louis - B2SL

June 18, 1974

Returned PCB - Westinghouse

F.G. Benignus

T.L. Gossage

W.B. Papageorge - B1ND

E.M. Potter - B2MK

G. Paton

Attached are some pictures of a shipment of Inerteen waste for incineration from Westinghouse at Bloomington. This shipment fails to meet an acceptable standard in several ways.

- (1) Loose and missing bungs, and leakage on the trailer floor with sawdust applied.
- (2) Use of open head drums with clamped lids. These cannot be kept tight.
- (3) Solids, apparently floor sweepings, in the bottom of the drums. (The board is ours - to illustrate the problem.)

Some details, including the names of the Westinghouse inspectors, are written on the back.

We cannot accept a repeat of this situation.

J. R. Savage

/b1  
Att.(only CP)

0007194

PCB-ARCH0006855