

P81C

ABERDEEN CHEMICAL PLANTINDUSTRIAL HYGIENE MONTHLY REPORT

Month: September, 1986

Date of Report: October 27, 1986

I. ROUTINE CHEMICAL DOSIMETRYAll Sample Results

<u>CHEMICAL</u>	<u>< PEL</u>		<u>> PEL (OVEREXPOSURES)</u>	
	<u>NO.</u>	<u>%</u>	<u>NO.</u>	<u>%</u>
VCM	82	98.8	1	1.2
Lead	20	95.2	1	4.8
Total Particulates	5	100.0	0	0.0

Overexposures

<u>JOB CLASS</u>	<u>EXPOSURE</u>	<u>SOURCE</u>
General Mechanic	3.1* ppm, VCM	Employee overexposed while repairing a leak at the VCM compressor shed.
Compounder	53.6* Micrograms Lead/M ³	Employee overexposed while charging Line I blenders. The exact cause of his overexposure has not yet been determined.

* Respiratory protection was worn.

II. EMPLOYEE ANNUAL HEALTH TRAINING

Eight, annual health training classes were held. The training included OSHA required instruction related to VCM, lead, asbestos, noise, and respiratory protection.

III. MAINTENANCE PERSONNEL LEAD EXPOSURE


The Maintenance worker lead dosimetry program continued through the month. The measurements, using the same protocols as with routine, Compound/Dry Blend personnel lead dosimetry, are made as maintenance work within potential lead exposure areas is performed. The results for the month are as follows:

<u>Job Class</u>	<u>TWA Result (Micrograms Lead/M³)</u>	<u>PEL (Micrograms Lead/M³)</u>
General Mechanic	4.1	50.0
General Mechanic	6.0	50.0
General Mechanic	< 5.4	50.0

Industrial Hygiene Monthly Report
Page 2

III. MAINTENANCE PERSONNEL LEAD EXPOSURE - continued

<u>Job Class</u>	<u>TWA Result (Micrograms Lead/M³)</u>	<u>PEL (Micrograms Lead/M³)</u>
General Mechanic	13.8	50.0
General Mechanic	< 4.2	44.4
General Mechanic	< 4.5	47.1


Jerald V. Uptain

rah

c: JF, JWW, DWH, PJK, WFH, TFL, VEM, RAF, AHS, CWT
Tom Grumbles, J. R. Drumwright, M.D. - Houston

