

CMS REPORT NO. 055
PROGRAM CMS8CM65

EMPLOYEE ENVIRONMENTAL EXPOSURE PROFILE

REPORT DATE 02/20/90
PAGE 209

PLANT: 1400 HENRY CHEM PLT 309-364-2311
EMPLOYEE:

DEPARTMENT: 5537 PVC DISPERSION

YEAR: 1989

JOB CODE	JOB NAME	EXP		STD											
EXPOSURE CDE	NAME	LV	RANGE	AVG	DEV	UNITS	SAMPLES	DATE	SHIFT	LENGTH	TWA	VALID	PROTECTION		

14005537ZZ JOB AS TASK OF PVC PROD.OPER.- PEARL CHARGE OPER.

00148 VINYL CHLORIDE 1910.1017

INDIVIDUAL MONITORING: PPM 01/17/89 A 600 0.25 4 NONE WORN

INDIVIDUAL MONITORING: PPM 04/28/89 A 600 0.25 4 NONE WORN

99917 TRAINING - OSHA HAZARD COMMUNICATION

INDIVIDUAL MONITORING: 12/20/89 60 0.00 0 NONE WORN

99919 TRAINING - HEARING CONSERVATION

INDIVIDUAL MONITORING: 11/16/89 A 35 0.00 0 NONE WORN

99930 TRAINING - RESPIRATOR USE

INDIVIDUAL MONITORING: 05/04/89 40 0.00 0 NONE WORN

NGC 08755

WZ

REPORT DATE 05/11/89
PAGE 141

YEAR: 1988

JOB CODE	JOB NAME	EXP	STD										
EXPOSURE CDE	NAME	LVL	RANGE	AVG	DEV	UNITS	SAMPLES	DATE	SHIFT	LENGTH	THA	VALID	PROTECTION

14005537ZZ JOB AS TASK OF PVC PROD.OPER.- PEARL CHARGE OPER.

B0001 NOISE, 80/90-5

INDIVIDUAL MONITORING:	PCNT	06/07/88	A	600	34.08	0	HEARING MUFFS
------------------------	------	----------	---	-----	-------	---	---------------

00148	VINYL CHLORIDE	1910.1017
-------	----------------	-----------

INDIVIDUAL MONITORING:	PPM	01/19/88	A	600	0.25	0	NONE WORN
------------------------	-----	----------	---	-----	------	---	-----------

INDIVIDUAL MONITORING:	PPM	04/29/88	A	600	0.25	4	NONE WORN
------------------------	-----	----------	---	-----	------	---	-----------

INDIVIDUAL MONITORING:	PPM	10/14/88	A	600	0.27	0	NONE WORN
------------------------	-----	----------	---	-----	------	---	-----------

NGC 08756

P96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/87 TO 12/31/87 DATE 02/25/88 TIME 083727 PAGE 1

CHEMICAL M1 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP	HEAR
HENRY	732	000	006	A	021887	600	.67		NO		0
HENRY	732	000	006	A	040387	600	.15	< D LIMIT	NO		0
HENRY	732	000	006	A	062687	600	.15	< D LIMIT	NO		0

NGC 08757

960000 - R.F.C. PERSONNEL MONITOR - PERSONAL DATA
01/01/86 TO 12/31/86 DATE 03/09/87 TIME 093257 PAGE 1

CHEMICAL KI MALE

LAST NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP	PCS	GRK	TH	RESP	FEAR
ENRY	722	000	006	A	061086	600	.27					C	

NGC 08758

R96846C - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/85 TO 12/31/85 DATE 05/01/86 TIME 092054 PAGE 1

CHEMICAL M1		MALE	
PLANT NAME	AREA TASK JOB SHIFT DATE	E/T	..PPM
HENRY	732 000 006 A 051685	600	.26
		PUMP PDS	BRK TH RESP HEAR
		ND	0

1968460 - R.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/84 TO 12/31/84 DATE 02/01/85 TIME 152103 PAGE 1

CHEMICAL M1 MALE

PLANT NAME.....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP	HEAR
HENRY	732	000	006	A	012384	600	.60	OUT MASK		0	

NGC 08760

SD - R.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/82 TO 12/31/82 DATE 02/09/83 TIME 150512 PAGE 1

CHEMICAL M1 MALE

NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP
	732	000	012	A	011182	360	.07	OUT MASK	NO	0
	732	000	012	A	040182	360	.01	OUT MASK	NO	0

NGC 08761

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/81 TO 12/31/81 DATE 01/10/86 TIME 105352 PAGE 1

							CHEMICAL	M1		MALE				
PLANT NAME	AREA	TASK	JOB	SHIFT	DATE	E/T	PPM	PUMP	POS	BRK	TH	RESP	HEAR	
HENRY	732	000	012	A	090381	600	.03	OUT	MASK	>20%		0		
HENRY	732	000	012	A	100781	600	.03	OUT	MASK	NO		0		
HENRY	732	000	012	A	110381	360	.04	OUT	MASK	NO		0		
HENRY	732	000	012	A	120181	360	.11	OUT	MASK	NO		0		

NGC 08762

R968460 - R.F.C. PERSONNEL MONITOR - PERSONAL DATA
 01/01/80 TO 12/31/80 DATE 02/17/81 TIME 141721 PAGE 1

					CHEMICAL	MI	MALE						
PLANT NAME----	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP	PDS	BRK	TH	RESP	
HENRY	731	023	010	R	073080	020	2.08	OUT	MASK	NO		2	
HENRY	731	023	010	R	073080	028	3.92	OUT	MASK	>20%		2	
HENRY	731	000	010	R	073180	360	.18	OUT	MASK	NO		0	
HENRY	731	000	010	R	091380	360	.10	OUT	MASK	NO		0	

NGC 08763

R968460 - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/79 TO 12/31/79 DATE 03/27/80 TIME 115946 PAGE 1

CHEMICAL D MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	.MG/M3	PUMP POS	BRK TH	RESP
HENRY	741	COO	023	A	090579	360	2.35			C

NGC 08764

DISTRIBUTION ATTENTION M.I.S. DEPARTMENT

* B F *

R96846 VCM MONITORING - PERSONAL RECORD

DATE 01/15/76

---FROM 01/01/75 TO 12/31/75

PLANT NAME	SPL PERIOD	AREA	TASK	JOB	SHIFT	DATE	EXP	TIME	PM-VCN	R
HENRY	LONG	731	000	014	D	013175	240		0.92	1
HENRY	LONG	731	000	015	C	041875	240		1.20	1
HENRY	LONG	731	000	015	C	052775	240		1.30	2
HENRY	LONG	731	000	023	A	062575	240		0.00	0
HENRY	LONG	741	000	023	A	072375	240		0.03	0
HENRY	LONG	741	000	023	A	082975	240		0.00	0
HENRY	SHORT	731	021	015	C	052575	30		27.09	2
HENRY	SHORT	731	004	017	B	061175	12		21.00	2
HENRY	SHORT	731	026	017	B	061375	7		1.70	0

NGC 08765