

ABD00344804

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY CARD (A)
SAMPLE **No** 0193Hazard: VCM (✓) Lead () Noise () () Date 12/2/79Name Larry Frye S. S. # 416-74-1049 Shift CDepartment Wing Job Class chief oper. lgr

	Start	Stop
Instrument No. <u>304</u>	Time <u>6:30</u> AM (☒) PM ()	<u>7:00</u> AM () PM (☒)
Noise Cell No. _____	Airflow _____	_____

Analyst: [Signature] Analysis Date: 12-5-79

Hazard	TWA Exposure	
VCM	PEL: 1 PPM	<u>0.1</u> PPM
Noise	Over () Under () 115 dBA	% of PEL
Lead (Micrograms)	TOT: PEL: Per M ³	Per M ³

ABD00344805

CONOCQ CHEMICALS - ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)

SAMPLE No 0193

Hazard: VCM (☒) Lead () Noise () () Date 12/2/19

Time Clock (Lead Sampling Only) : IN: _____ AM() PM() OUT: _____ AM() PM()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
Rx area	6 hrs		
Pxyer area	6 hrs		

List most likely causes of possible overexposure to the hazard.

1. Rx area
- 2.
- 3.

Check respiratory protection you used:

(☒) None () Dust Mask () Air-line Respirator () Scott Air-pak

Signature

Harry Frye

Please complete and return to guard