

MD-3-A

PACKAGE TICKET

(DRY AND PASTE ONLY)

CODE

BT 425

LOT

E 1080

NET WT/PKG

NO. PKG

PACK. WGT

LOCATION

PO

18

2898

19-43

STUMP

LAMP

2889

TOTAL NET WT.

2898

PKG. N-CODE

PROD. SPVR.

DATE

WHSE. OPER.

WK

5/5/1

2882

D.T

165.+
160.+
169.+
160.+
161.+
165.+
117.+
164.+
171.+
169.+
175.+
170.+
170.+
168.+
165.+
160.+
173.+
116.+
2898.T

37
204

CG 20 CODE BT-425-D PKG. _____

→ MAY -0.81-21080

EST. WGT. _____ 2866 LBS.

18

PROCESSING INSTRUCTIONS: BATCH UNIT

PROCESSES BT-425-D (F) APPROVED BY AJC 06-29-77
DCG 06-30-77

TYPED BY
emw070677

MAKING NOTES

REMARKS

NAME: MONASTRAL® BLUE BF

NON-BLEEDING

INSTRUCTIONS

-PRESSING-

RECORD

VAT					204	PRESSLOAD	1ST	2ND	3RD	4TH	5TH
DATE					5.4	STARTED	5 AM				
TIME					5:30	CAKES USED	60				
RELEASED BY					3935	WATER ON	1/2				
PRESS	20	21	26	35	6062	HRS. WASHED	13/2				
NO. OF CAKES	3 x 48	3 x 42	4 x 44	60		OHMS	5000				
PRESS	with	AGITATION				HRS. WASHED					
WASH TO	5000	OHMS with 35-75°F water				OHMS					
TEST AFTER	3	HOURS				HRS. WASHED					
LOAD on 8 cars						OHMS					
						CAKE CONDITION					
						NO. CARS LOADED	9				
						EXPLAIN LOSSES					

SAMPLES
DELIVER TO

SAMPLED BY

RELEASED BY

-DRYING-

Dry 20 hrs at 220°F	LUMP: - OK - WET - SALTS - CONTAMINATED
20	
	ADDITIONAL DRYING HOURS REQUIRED
	No. Drums: 17
SAMPLES	NO. CARS PULLED
DELIVER TO	SAMPLED BY
	LUMP WGT. 2889
	RELEASED BY R14

-GRINDING-

MILL 7 or 8 LSP 3/32" RP SCREEN 1750 RPM	SCREEN	RPM
MAX. TEMP. 200°F	MAX. TEMP.	°F
	EXPLAIN LOSSES	
SAMPLE WITHOUT MIXING	DATE MIXED 5/8/81	
SAMPLES 1 Env & 2 Pt Cans		
DELIVER TO C.T.L.	SAMPLED BY 22/11	RELEASED BY

DUP050097500

1180.
51
225

0.00 *

17 DRUMS

1.90 +
0.14 +
1.83 +
0.14 +
1.93 +
0.14 +
1.97 +
0.14 +
1.92 +
0.14 +
1.73 +
0.14 +
1.90 +
0.14 +
1.90 +
0.14 +
1.85 +
0.14 +
1.86 +
0.14 +
1.87 +
0.14 +
1.88 +
0.14 +
1.64 +
0.14 +
22.36 *

1080
41
100

22.36 +
1.65 +
0.14 +
1.91 +
0.14 +
1.70 +
0.14 +
1.83 +
0.14 +
28.89 *
28.89M+

5/7

N-8862-A, N-8863-A, N-8900-A

HIGH SOLIDS PRESSCAKE

- NEWPORT SHIPPING THE ABOVE
IN PRESSCAKE OR SLURRY FORM
- AFTER REMOVING TOTE LID,
CHECK TOTE CONTENTS AS TO
WHETHER MATERIAL IS IN
PRESSCAKE OR SLURRY FORM
- IF PRESSCAKE FORM, PRESET
WATER METER AT 250 GAL-WATER
USE MODE #4 FOR PUMPING
FULL TOTES & MODE #1 FOR
STUMPING TOTES
- IF SLURRY FORM, TREAT
AS PER CARD