

EATON *To: Glen Hoch* Internal Correspondence

Date: June 22, 1990

To: R. Wolfarth
Axle/Brake - Henderson

Copy: See Below

From: Lanny Whitlow - Axle & Brake - Glasgow

Subject: Asbestos Shoe & Lining Assemblies for Navistar

cc: *P. Sloan* / 26

D. Lord

Better move now.

The inventory of 1001042 asbestos lining for Navistar brake assemblies 807586 and 807587 will be exhausted by the end of November 1990 based on June 15 MRP. Once this lining is gone, we will not be able to supply these brake assemblies to Navistar unless they convert to a non-asbestos lining.

Please relay this information to the proper individuals so a suitable replacement can be engineered prior to the stock-out date.

If you have any questions, please call.

Lanny Whitlow
Lanny Whitlow

LW/ss

Distribution:

- M. Barron - Glasgow
- B. Bryant
- B. Carey
- J. Chappell
- D. Doty
- D. Miller
- J. Tomko

B. Buckman - Henderson

RECEIVED
JUN 29 1990
TO: *Rom Wolfarth*, Lanny Whitlow, Dick Lord
cc: *R. Young*

Navistar engineering has been contacted and is shocked they still had asbestos linings in use. The situation is pure oversight. They will issue a new Bill of Materials for the brakes immediately. Prepare to scrap the remaining assemblies, as it is highly unlikely they will allow an "exhaust" for the current part numbers.

INITIAL	ENG	ENTRY	PRICE	SALES ORD	SCHED
DATE					

Pt Sloan

EAB 083305

SCF-EC-3850