

May 2, 1951

Dr. Lloyd E. Hamlin, Medical Director
American Brake Shoe Company
2501 Blue Island Avenue
Chicago 8, Illinois

Dear Doctor Hamlin:

We have been asked by the American Crucible Products Company of Lorain, Ohio to make a study of their non-ferrous foundry and to suggest modifications and new equipment which might enable them to do a better and safer job.

Knowing that you have already dealt with this problem, we wonder if you and American Brake Shoe management would object to my visiting one or more of your foundries to learn how the job should be done.

I recall from your talk here that you do not consider the problem completely solved, but that you have made some basic improvements in equipment and operations. It is these things which we are anxious to learn about and, with your permission, pass on. Any suggestions you might have will be appreciated.

Very truly yours,

Lester B. Roberts

LBK ef

C.C.: Dr. Robert A. Kehoe

KE 0021675