

PLAINTIFF'S EXHIBIT

ASA-582

JBR file

MOV _____
RDP _____
LDW _____
SGC _____
SDB _____
DAR _____

El Paso, Texas
December 6, 1976

MEMORANDUM TO: Mr. M. O. Varner ✓
Dept. of Environmental Sciences
Salt Lake City Office

CASE 15-876
From M. O. Varner
Coded for K. A. [unclear]
RCB

FROM: J. B. Richardson

RE: MONTHLY ACTIVITY SUMMARY - NOVEMBER, 1976

- A. Continue respirator training sessions initiated in October, 1976.
- B. Lead Hygiene Program
 - 1. Check respirators and fit of those on alert list.
 - 2. Obtain resamples for B. Salcido (#1410) and R. Menchaca (#1283).
- C. Perform stack testing at the Acid Plant (11/9-12/76 and 11/30-12/3/76) to comply with TACB sampling requirements.
- D. Tour Phelps-Dodge Copper Refinery in El Paso, Texas.
- E. Check skin irritation on P. Diaz (#2243) and F. Luna (#1578), who had discarded their respirator facelets.
- F. Asbestos Program
 - 1. Continue to document asbestos use in the plant.
 - 2. Assist in selecting asbestos substitute for lab use.
 - 3. Meet with Mr. Ray Powell of Johns-Manville to discuss J-M's line of asbestos substitutes.
- G. Travel to Whiting Plant to appear for ASARCO at the Workmen's Compensation trial of Claude Jackson.
- H. Attend ASSE (American Society of Safety Engineers) Seminar at the El Paso Airport Hilton.
- I. Vacation (11/22-26).

JBR/cb
cc: WRKelly
JPSieversen
CEDungey

John B. Richardson
JOHN B. RICHARDSON
Environmental Scientist

ASARCO ELP 0000106