

FRICION MATERIALS STANDARDS INSTITUTE, 588 MONROE TURNPIKE, MONROE, CT 06468
A U T O M O T I V E D A T A B O O K B U L L E T I N #3-971
January 16, 1998

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>				
1998, CL		7345-D465**	D/D	7418-D537**
	OR	7382-D503**	D/	
1998, Integra		7493-D617**	D/D	7443-D564**
1998, NSX		7382-D503**	D/D	7383-D504**
1998, RL		7382-D503**	D/D	7418-D536**
1998, TL		7382-D503**	D/D	7418-D537**
<u>CHEVROLET</u>				
1998, Camaro		7618-D749**	D/D	7619-D750**
		(Notes #5 & #14)		(Notes #6 & #15)
1998, Prizm		7441-D562**	D/N	8105-597*
<u>CHRYSLER</u>				
1998, Town & Country		7470A-D642	D/N	1485ATT-S714
	OR		/D	7424-D751**
				(Notes #1 & #16)
<u>DODGE</u>				
1998, Avenger		7365-D484**	D/N	1445-S658*
	OR		/D	7272-D383**
1998, Neon		7518A-D642	D/N	1473-S689*
	OR		/D	7438B-D641
1998, Stratus		7530A-D650	D/N	1481-S716
	OR		/D	7438B-D641
1998, Caravan		7470A-D642	D/N	1485ATT-S714
	OR		/D	7424-D751**
1998, Grand Caravan		7470A-D642	D/N	1485ATT-S714
	OR		/D	7424-D751**
<u>DODGE TRUCK</u>				
Durango	1998	7616-D746**	D/	
		(Notes #3 & #11)		
Dakota	1998	7410A-D529	D/BH	2176T-538
	OR		/BH	2089T-445*
Ram 1500	1998	7259-D369**	D/BH	2134BTT-S652
Ram 2500	1998	7260-D370**	D/BH	2042BT-S655
Ram 3500	1998	7339-D459**	D/BH	2157AT-S656
<u>EAGLE</u>				
1998, Talon		7365-D484**	D/N	1445-S658*
1998, Talon 4WD		7412-D530**	D/D	7272-D383**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>FORD</u>			
1997-95, Contour	7528-D745**	D/	
	(Note #10)		
1998, Crown Victoria	7617-D748**	D/	
	(Notes #4 & #13)		
<u>HONDA</u>			
1998, Accord Coupe	7345-D465**	D/N	1429-S627*
OR		/D	7418-D537**
1998, Accord Sedan	7345-D465**	D/N	1429-S627*
OR		/D	7418-D537**
1998, Civic	7573-D465**	D/N	1364-576*
1998, Odyssey	7382-D503**	D/D	7418-D536**
OR	7439-D560**	D/	
1998, Passport	7585-D579**	D/N	1360-S619*
OR		/D	7586-D580**
1998, Prelude	7382-D503**	D/D	7418-D537**
<u>HYUNDAI (See Comments)</u>			
1998, Sonata	7329-D747**	D/N	1400-S708*
	(Note #12)		
OR		/D	7236-D342**
<u>INFINITI</u>			
1998, I30	7318-D653**	D/D	7533-D540**
1998, Q45	7566-D691**	D/D	7468-D588**
<u>ISUZU</u>			
1998, Rodeo	7585-D579**	D/N	1360-S619*
OR		/D	7586-D580**
<u>JEEP</u>			
1998, Cherokee	7358-D712**	D/BH	2176T-538
OR		/D	7502-D713**
1998, Grand Cherokee	7358-D712**	D/D	7502-D713**
1998, Wrangler	7358-D712**	D/BH	2176T-538
OR		/D	7502-D713**
<u>KIA</u>			
1998, Sephia	7529-D649**	D/N	1493-S697*
OR		/D	7568-D693**
<u>MAZDA</u>			
1998, Millenia	7520-D643**	D/D	7521-D553**
1998, B2500	7532-D652**	D/BH	2180T-S704
OR		/BH	2089AT-S705
1998, B3000	7532-D652**	D/BH	2180T-S704
OR		/BH	2089AT-S705
1998, B4000	7532-D652**	D/BH	2180T-S704
OR		/BH	2089AT-S705
<u>MERCURY</u>			
1997-95, Mystique	7528-D745**	D/	
1998, Grand Marquis	7617-D748**	D/	

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>MITSUBISHI FUSO</u>				
FH 211	1997-96	1501-S730 (Notes #7 & #17)	N/N	1502-S731 (Notes #8 & #18)
<u>NISSAN</u>				
1998, Frontier		7228-D333**	D/N	1399-574*
	OR		/N	1433-S631*
1998, Quest		7456-D576**	D/N	1452-S665
<u>PLYMOUTH</u>				
1998, Breeze		7530A-D650	D/N	1481-S716*
	OR		/D	7438B-D641
1998, Neon		7518A-D642	D/N	1473-S689*
	OR		/D	7438B-D641
1998, Prowler		7597-D730**	D/D	7598-D730**
1998, Voyager		7470A-D642	D/N	1485ATT-S714
	OR		/D	7424-D751**
1998, Grand Voyager		7470A-D642	D/N	1485ATT-S714
	OR		/D	7424-D751**
<u>PONTIAC</u>				
1998, Firebird		7618-D749**	D/D	7619-D750**
<u>PORSCHE</u>				
1998, Boxster		7606-D737**	D/D	7607-D738**
<u>SAAB</u>				
1998, 900		7605-D736**	D/D	7614-D709**
<u>SUZUKI</u>				
1998, Esteem		7557-D677**	D/N	1461-S630*
1998, Swift		7331-D451**	D/N	1489-S724*
<u>TOYOTA</u>				
1998, Sienna		7615-D744**	D/	
		(Notes #2 & #9)		
1998, 4 Runner		7298-D611**	D/N	1397-589*
1998, Land Cruiser		7298-D502**	D/D	7487-D606**
1998, Rav 4		7441-D695**	D/N	1447-587*
1998, T100 1/2T, 2WD		7485-D686**	D/N	1397-589*
1998, T100 1T, 2WD		7486-D605**	D/N	1383-549*
1998, Tacoma 2WD		7548-D433**	D/N	1358-505*
1998, Tacoma 4WD		7549-D436**	D/N	1397-589*

C O M M E N T SExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
7329	7329-D747	1998 Hyundai Sonata Front
7528	7528-D745	1997-95 Ford Contour Front
		1997-95 Mercury Mystique Front

DISC BRAKE LINING ASSIGNMENTS


Note #1	<u>FMSI 7424</u>	7424-D751
	40.1 x 15.9 x 123.0	4 IM
	(1.58 x .626 x 4.84)	

Note #2	<u>FMSI 7615</u> 52.1 x 17.0 x 122.2 (2.05 x .669 x 4.81)	7615-D744 4 IM
Note #3	<u>FMSI 7616</u> 47.0 x 20.2 x 167.1 (1.85 x .795 x 6.58)	7616-D746 4 IM
Note #4	<u>FMSI 7617</u> 64.0 x 16.4 x 144.0 (2.52 x .646 x 5.67)	7617-D748 4 IM
Note #5	<u>FMSI 7618</u> 49.1 x 14.7 x 166.9 (1.93 x .579 x 6.57)	7618-D749 4 IM
Note #6	<u>FMSI 7619</u> 31.2 x 16.6 x 99.6 (1.23 x .653 x 3.93)	7619-D750 4 IM


DRUM BRAKE LINING ASSIGNMENTS

Note #7	<u>FMSI 1501</u> 320.0dd - 120.0 x 11.6 x 153.7 (12.60 - 4.72 x .457 x 6.05)	1501-S730 8 - 48
Note #8	<u>FMSI 1502</u> 320.0dd - 140.0 x 11.6 x 155.0 (12.60 - 5.51 x .457 x 6.10)	1502-S731 8 - 48


DISC BRAKE SHOE ASSIGNMENTS

Note #9	 <u>FMS D744</u> 141.0 x 6.7 (5.55 x .264)	7615-D744 Toyota
Note #10	 Inner <u>FMS D745</u> 155.2 x 5.6 156.5 x 5.1 (6.11 x .220) (6.16 x .201)	 Outer 7528-D745 Ford Mercury

DISC BRAKE SHOE ASSIGNMENTS (con't)

				
			Inner	Outer
Note #11	<u>FMS D746</u>			7616-D746
	192.0 x	5.9		Dodge
	192.0 x	5.9		
	(7.56 x	.232)		
	(7.56 x	.232)		



				
			Inner	Outer
Note #12	<u>FMS D747</u>			7329-D747
	137.2 x	6.1		Hyundai
	137.2 x	6.1		
	(5.40 x	.240)		
	(5.40 x	.240)		

				
Note #13	<u>FMS D748</u>			7617-D748
	165.1 x	6.4		Ford
	(6.50 x	.252)		Mercury

				
Note #14	<u>FMS D749</u>			7618-D749
	182.6 x	5.2		Chevrolet
	(7.19 x	.205)		Pontiac

				
			Inner	Outer
Note #15	<u>FMS D750</u>			7619-D750
	121.4 x	6.1		Chevrolet
	121.4 x	6.1		Pontiac
	(4.78 x	.240)		
	(4.78 x	.240)		

DISC BRAKE SHOE ASSIGNMENTS (con't)

			
		Inner	Outer
Note #16	<u>FMS D751</u>		7424-D751
	155.6 x 5.0		Chrysler
	155.6 x 5.0		Dodge
	(6.12 x .197)		Plymouth
	(6.12 x .197)		

DRUM BRAKE SHOE ASSIGNMENTS

			
Note #17	<u>FMS S730</u>		1501-S730
	320.0 x 120.0		Mitsubishi Fuso
	(12.60 x 4.72)		

			
Note #18	<u>FMS S731</u>		1502-S731
	320.0 x 140.0		Mitsubishi Fuso
	(12.60 x 5.51)		

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover, SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.