

**WARNINGS IN SHOP MANUALS
(Asbestos Cases)**

The following is a review of Ford Motor Company car and truck shop manuals from 1950 to 1982 directed to any warnings in the manuals about asbestos dust in brake repairs. Since much of the language is repeated from year to year and within the various shop manuals issued in any given year, samples of each type of warning (or lack thereof) are attached as exhibits A through I. Reference will be made to a particular exhibit and the language contained therein.

1970	Car	Volume 1	12-01-08	A
1974	Car	Volume 1	12-01-12	A
1975	Car	Volume 1	12-01-23	A
1975/76	Car	Volume 1	12-01-24	A
1977	Car	Volume 1	12-01-29	B
1977	Truck	Volume 1	12-01-22	C
1978	Car	Volume 1	12-01-32	D
1978	Truck	Volume 1	12-01-22	C
1979	Car	Volume 1	12-01-31	D
1980	Light Truck	BCE*	12-01-20	E
1980	Medium/Heavy Truck	BCE	12-01-20	E
1980	Fairmont/Zephyr T-Bird/Cougar	BCE	12-01-22	D
1980	Pinto/Bobcat Mustang/Capri Granada/Monarch/ Versailles	BCE	12-01-28	D
1980	Ford/Mercury Lincoln Continental/ Continental/Mark VI	BCE	12-01-20	E
1981	Lincoln	BCE	12-01-22	E
1981	Escort/Lynx	BCE	12-01-27	F
1981	Light Truck	BCE	12-01-18	E
1981	Medium/Heavy Truck	BCE	12-01-24	E
1981	Courier	BCE	12-01-6	A



005222

PRODUCED BY FORD

