

A U T O M O T I V E D A T A B O O K B U L L E T I N #2-931

November 16, 1993

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>			
1994, Integra	7493-D617** (Notes #1 & #14)	D/D	7443-D564**
<u>ALFA ROMEO</u>			
1993-90, 164	7469-D590**	D/D	7498-D228** (Note #6)
<u>BMW</u>			
1994, 530i	7284-D394**	D/D	7286-D396**
1994, 540i	7284-D394**	D/D	7286-D396**
<u>BUICK (See Comments)</u>			
1994, LeSabre	7384-D623** (Note #20)	D/	
1994, Park Avenue	7384-D623**	D/	
<u>CHEVROLET (See Comments)</u>			
1994, Lumina Minivan	7384-D623**	D/	
<u>CHEVROLET TRUCK/GMC TRUCK (See Corrections & Comments)</u>			
1993, C1500		/N	1404A-S675 (Note #22)
1993, K1500		/N	1404A-S675
<u>DODGE (See Corrections)</u>			
1993, Colt 4DR		/N	1415-S677* (Note #24)
1993-92, Colt Vista		/N	1415-S677*
<u>DODGE TRUCK</u>			
1994, Ram 1500	7259-D369**	D/BH	2134ATT-S652
1994, Ram 2500	7260-D370**	D/BH	2042BT-S655
1994, Ram 3500	7339-D459**	D/BH	2157AT-S656
1994, Ram 1500 (4WD)	7259-D369**	D/BH	2134ATT-S652
1994, Ram 2500 (4WD)	7260-D370**	D/BH	2042BT-S655
	OR 7339-D459**	D/	
1994, Ram 3500 (4WD)	7339-D459**	D/BH	2157AT-S656
<u>EAGLE (See Corrections)</u>			
1993, Summit 4DR		/N	1415-S677*
1993-92, Summit Wagon		/N	1415-S677*

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright® by Friction Materials Standards Institute, Inc.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>FORD (See Comments & Corrections)</u>			
1994, Crown Victoria Police	7501A-D499 (Note #9)	D/	
1993, Escort		/N	1463-S678*
1994, Taurus	7479-D601**	D/	(Notes #11 & #25)
<u>GEO (See Corrections)</u>			
1993, Prism		/N	8105-597*
<u>HONDA</u>			
1993, Civic Ex	7497-D621** (Notes #5 & #18)	D/D	7443-D564**
<u>ISUZU (See Corrections)</u>			
1993, Amigo	7347-D363**	D/N	1360-S619*
OR		/D	7328-D398**
1993, Pick-Up	7347-D363**	D/N	1360-S619*
OR		/D	7328-D398**
<u>LEXUS</u>			
1993, GS300	7495-D619** (Notes #3 & #16)	D/D	7452-D572**
<u>MERCEDES</u>			
1992-90, 300E	7311-D423**	D/D	7496-D620** (Notes #4 & #17)
<u>MERCURY (See Comments & Corrections)</u>			
1994, Grand Marquis Police	7501A-D499	D/	
1994, Sable	7479-D601**	D/	
1993, Tracer		/N	1463-S678*
1992-91, Tracer		/N	1407-598*
<u>MITSUBISHI (See Corrections)</u>			
1993-92, Galant		/N	1415-S677*
1993, Mirage 4DR		/N	1415-S677*
1993-92, Expo		/N	1415-S677*
1993-92, Expo LRV		/N	1415-S677*
<u>MITSUBISHI FUSO (See Comments)</u>			
1988-87, FE Series	7499-D624** (Notes #7 & #21)	D/	
1993-89, FE Series (Dual Caliper)	7500-D433** (Note #8)	D/	
<u>NISSAN (See Corrections)</u>			
1987(Early)-85, Maxima	7171-D266**	D/D	7146-D323**
<u>OLDSMOBILE (See Comments)</u>			
1994, Eighty Eight	7384-D623**	D/	
1994, Ninety Eight	7384-D623**	D/	
1994, Silhouette	7384-D623**	D/	
<u>PLYMOUTH (See Corrections)</u>			
1993, Colt 4DR		/N	1415-S677*
1993-92, Colt Vista		/N	1415-S677*

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>PONTIAC (See Comments & Corrections)</u>			
1994, Bonneville	7384-D623**	D/	
1994, Trans Sport	7384-D623**	D/	
1993, LeMans		/N	1405-594*
<u>SUBARU</u>			
1993, Impreza	7442-D563**	D/N	1462-S676*
			(Note #10 & #23)
OR	7350-D470**	D/D	7351-D471**
<u>TOYOTA (See Corrections)</u>			
1992-91, Cressida		/D	7319-D622**
			(Note #19)
1993, Previa	7380-D615**	D/N	1358-505*
	(Note #12)		
OR	7408-D616**	D/D	7381-D501**
	(Note #13)		
<u>VOLVO</u>			
1993, 850	7494-D618**	D/D	736-D31**
	(Notes #2 & #15)		

C O M M E N T SExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
1404A	1404A-S675	1993 Chev Truck/GMC Truck Rear
1415	1415-S677	1993 Dodge/Plymouth Colt 4DR Rear
		1993-92 Dodge/Plymouth Colt Vista
		1993 Eagle Summit 4DR Rear
		1993-92 Eagle Summit Wagon Rear
		1993-92 Mitsubishi Galant Rear
		1993 Mitsubishi Mirage 4DR Rear
		1993-92 Mitsubishi Expo Rear
		1993-92 Mitsubishi Expo LRV Rear
7319	7319-D622	1992-91 Toyota Cressida Rear
7380	7380-D615	1993 Toyota Previa Front
7384	7384-D623	1994 Buick LeSabre Front
		1994 Buick Park Avenue Front
		1994 Chevrolet Lumina Minivan Front
		1994 Oldsmobile Eighty Eight Front
		1994 Oldsmobile Ninety Eight Front
		1994 Oldsmobile Silhouette Front
		1994 Pontiac Bonneville Front
		1994 Pontiac Trans Sport Front
7408	7408-D616	1993 Toyota Previa Front

Existing shoe with new lining:

<u>Shoe</u>	<u>Assembly</u>	<u>Application</u>
D228	7498-D228	1993-90 Alfa Romeo 164 Rear
D433	7500-D433	1993-89 Mitsubishi Fuso Front
D499	7501A-D499	1994 Ford Crown Victoria Police Front
		1994 Mercury Grand Marquis Police Front

C O R R E C T I O N S

Chevrolet Truck/GMC Truck - 1993 Catalogs shows incorrect rear drum brake as FMS 1404A-S654. The correct listing is FMS 1404A-S675.

Ford - 1993 Ford Escort and Mercury Tracer Rear drum brake is incorrect as cataloged in 1993 Data Book. The correct assignment is FMSI 1463-S678.

1992-91 Mercury Tracer rear drum brake is incorrect as cataloged in the 1993 Data Book. The correct assignment is FMSI 1407-598.

GEO - Bulletin #1-931 listed 1993 Prizm rear as 8105-D597. The correct listing is 8105-597.

Isuzu - 1993 Pick-Up cataloged incorrectly. The correct information is FMSI 7347-D363.

Nissan - Bulletin #1-931 listed 1982(Early)-85, Maxima. This was incorrect. The correct listing is: 1987(Early)-85, Maxima 7171-D266 front; 7146-D323 rear.

Pontiac - Bulletin #1-931 incorrectly listed 1993 LeMans rear brake as FMS 1404-594. The correct listing is 1405-594.

Toyota - Rear disc for 1992-91 Toyota Cressida is revised from FMSI 7319-D432 to 7319-D622.

FMSI 1415-610 was incorrectly cataloged for the following applications: 1993 Dodge/Plymouth Colt 4DR, 1993 Eagle Summit 4DR, 1993 Mitsubishi Mirage 4DR, 1993-92 Dodge/Plymouth Colt Vista, 1993-92 Eagle Summit Wagon, 1993-92 Mitsubishi Galant. The correct FMSI set is 1415-S677.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7493</u>					7493-D617
	49.8	x	16.4	x	117.0	4 IM
	(1.96	x	.646	x	4.61)	
Note #2	<u>FMSI 7494</u>					7494-D618
	51.8	x	18.6	x	114.3	4 IM
	(2.04	x	.732	x	4.50)	
Note #3	<u>FMSI 7495</u>					7495-D619
	55.1	x	17.0	x	122.9)	4 IM
	(2.17	x	.669	x	4.84)	
Note #4	<u>FMSI 7496</u>					7496-D620
	34.5	x	15.2	x	61.7)	4 IM
	(1.36	x	.598	x	2.43)	
Note #5	<u>FMSI 7497</u>					7497-D621
	50.2	x	16.4	x	116.1	4 IM
	(1.98	x	.646	x	4.57)	
Note #6	<u>FMSI 7498</u>					7498-D228
	40.9	x	16.5	x	67.2	4 IM
	(1.61	x	.650	x	2.65)	

DISC BRAKE LINING ASSIGNMENTS (con't)

Note #7	<u>FMSI 7499</u>	7499-D624
	52.8 x 16.5 x 147.3	4 IM
	(2.08 x .650 x 5.80)	
Note #8	<u>FMSI 7500</u>	7500-D433
	48.0 x 17.2 x 107.7	8 IM
	(1.89 x .677 x 4.24)	
	Note: O.E. set contains eight assemblies vehicle has two calipers/wheel.	
Note #9	<u>FMSI 7501A</u>	7501A-D499
	47.0 x 10.9 x 136.9	2 - 12
	45.5 x 9.6 x 162.0	2 - 12
	(1.85 x .429 x 5.39)	
	(1.79 x .378 x 6.38)	

DRUM BRAKE LINING ASSIGNMENTS

Note #10	<u>FMSI 1462</u>	1462-S676
	220.0dd - 35.0 x 4.0 x 220.0	4 Bonded
	(8.66 - 1.38 x .157 x 8.66)	
Note #11	<u>FMSI 1463</u>	1463-S678
	200.0dd - 35.0 x 4.3 x 192.0	4 Bonded
	(7.87 - 1.38 x .169 x 7.56)	

DISC BRAKE SHOE ASSIGNMENTS

Note #12	<u>FMS D615</u>	7380-D615	Toyota
	128.3 x 5.7		
	136.8 x 5.6		
	(5.05 x .224)		
	(5.39 x .220)		
Note #13	<u>FMS D616</u>	7408-D616	Toyota
	128.3 x 5.6		
	127.0 x 5.6		
	(5.05 x .220)		
	(5.00 x .220)		
Note #14	<u>FMS D617</u>	7493-D617	Acura
	129.0 x 6.5		
	(5.08 x .256)		
Note #15	<u>FMS D618</u>	7494-D618	Volvo
	156.5 x 5.6		
	(6.16 x .220)		
Note #16	<u>FMS D619</u>	7495-D619	Lexus
	144.0 x 6.0		
	(5.67 x .236)		
Note #17	<u>FMS D620</u>	7496-D620	Mercedes
	61.7 x 4.2		
	(2.43 x .165)		

DISC BRAKE SHOE ASSIGNMENTS (con't)

Note #18	<u>FMS D621</u> 136.7 x 6.6 (5.38 x .260)	7497-D621	Honda
Note #19	<u>FMS D622</u> 125.5 x 5.6 (4.94 x .220)	7319-D622	Toyota
Note #20	<u>FMS D623</u> 147.8 x 4.9 212.5 x 4.9 (5.82 x .193) (8.37 x .193)	7384-D623	Chevrolet Buick Oldsmobile Pontiac
Note #21	<u>FMS D624</u> 149.9 x 5.7 (5.90 x .224)	7499-D624	Mitsubishi Fuso

DRUM BRAKE SHOE ASSIGNMENTS

Note #22	<u>FMS S675</u> 254.0 x 57.0 (10.00 x 2.24)	1404A-S675	Chevrolet Truck GMC Truck
Note #23	<u>FMS S676</u> 220.0 x 35.0 (8.66 x 1.38)	1462-S676	Subaru
Note #24	<u>FMS S677</u> 203.2 x 35.0 (8.00 x 1.38)	1415-S677	Dodge Eagle Mitsubishi Plymouth
Note #25	<u>FMS S678</u> 200.0 x 35.0 (7.87 x 1.38)	1463-S678	Ford Mercury

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.