

0. C

1.23 +
1.41 +
1.15 +
1.13 +
1.33 +
1.26 +
1.21 +
1.13 +
1.11 +
1.27 +
1.20 +
1.39 +
1.22 +
1.28 +
1.31 +
1.29 +
1.22 +
1.11 +
1.22 +
1.28 +
1.28 +

021

26.03 4

PRODUCT NAME: WATCHUNG RED B

NON-BLEEDING DATE PRINTED: 9/22/82

CG 32 CODE RT-698-D PKG

PROCESSES APPROVED BY: RT-698-D (M) EWK 02/25/82

LOT K21149

COMTYP JOB NAME: 32RT698DPM

EST. WT. 2758 LBS.

MAKING NOTES:

INSTRUCTIONS

= PRESSING =

RECORD

VAT	DATE	TIME	RELEASED BY	PRESS	NO. OF Cakes	PRESS WITH	WASH TO	TEST AFTER	LOAD ON	CLEAN MAGNETIC SEPARATOR AFTER	PRESSING	CLEANED BY	TIME CLEANED	INSTRUCT MAKING TO ADD	HALFWAY THRU PRESSING	PRESSLOAD	STARTED	CAKES USED	WATER ON	HRS. WASHED	M MHOS	HRS. WASHED	M MHOS	HRS. WASHED	M MHOS	CAKE CONDITION	NO CARS LOADED	EXPLAIN LOSSES	1ST	2ND	3RD	4TH	5TH
	9-28-82	3:20 PM	E.M.	32	60	37	333 M MHOS	6 HOURS	12 CARS					10+ N-588-A																			

SAMPLES JAR
DELIVER TO

SAMPLED BY
RELEASED BY

= DRYING =

DRY 12 HOURS AT 220 F
THEN DRY 12 HRS AT 200 DEG F. HOLD
ON TRACK FOR 30 MIN BEFORE DUMPING.

LUMP: - OK - WET - SALTS - CONTAMINATED

ADDITIONAL DRYING HOURS REQUIRED

SAMPLES
DELIVER TO

NO CARS PULLED
SAMPLED BY
RELEASED BY

NO DRUMS
LUMP WGT 2645

= GRINDING =

MILL 2 LSP 0.066" RP SCREEN 1800 RPM
MAX. TEMP. 140 DEG F
INERT MILL WITH CO2 WHEN GRINDING
PER O.P. #0.F. 0043.

SCREEN RPM
MAX. TEMP. F

EXPLAIN LOSSES

SAMPLE WITHOUT MIXING
SAMPLES 2 ENV.
DELIVER TO CTL

DATE MIXED

SAMPLED BY
RELEASED BY

49
51
427

0.00 *

1.52 +

0.14 - ✓

1.46 +

0.14 - ✓

1.46 +

0.14 - ✓

1.40 +

0.14 - ✓

1.39 +

0.14 - ✓

1.06 +

0.14 - ✓

7.45 *

7.45 +
1.35 +
0.14 -
1.40 +
0.14 -
1.40 +
0.14 -
1.42 +
0.14 -
1.35 +
0.14 -
1.40 +
0.14 -
1.38 +
0.14 -
1.45 +
0.14 -
1.42 +
0.14 -
1.38 +
0.14 -
0.85 +
0.14 -
20.71 *

49	
51	
85	
	1.61 +
	0.14 -
	1.60 +
	0.14 -
	1.50 +
	0.14 -
	1.59 +
	0.14 -
	20.71 +
	26.45 *