

238

Port Hedland, 12th July 68.

The Manager,
Australian Blue Asbestos Pty Ltd.
Perth, W.A.

Dear Sir,
When Inspector Hunt returned from Eritenoon recently I questioned him regarding the matter of miners interfering with the spray systems provided at ore passes in the stopes. Mr Hunt informed me that he noticed several instances where the water hose had been disconnected and spraying was in progress.

In future, both Inspector Hunt and I will order the curtailment of all spraying operations in those stopes where sprays are either not fitted or are unworkable and will hold you, as Manager, responsible for the observance of Regs 150 (1), (2), & (3) of the Mines Regulations Act.

Could you please bring this matter to the attention of your Underground Manager and his Supervisors.

Yours faithfully,

DISTRICT INSPECTOR OF MINES, PORT HEDLAND.

PLAINTIFF'S
EXHIBIT
WV-04239

PLAINTIFF'S
EXHIBIT
10495.0

WV-004239