

THE DOW CHEMICAL COMPANY

TEXAS DIVISION
FRIEPORT TEXAS 77541

October 27, 1970

O. L. Dickson
O. N. Freeman
J. H. Moore
R. L. Silverthorne

cc: J. A. Barton
R. E. Flake, M. D.
B. S. Horvath

DUST - ASBESTOS SAMPLING

I have asked Jack Barton to set up to run Dust-Asbestos Sampling training program. I would like each of you to go through this training. It is the intent that you become qualified to make dust-asbestos surveys. Jack thinks that it will take about 6 half days to do this. Training will be Monday, Wednesday, and Friday afternoons, starting at 12:30 Friday, October 30, 1970, in Jack Barton's office.

I consider this to be high priority and hope you do not miss any of the training sessions.

R. C. Walker

R. C. Walker
Safety and Loss Prevention

ks
attachment

ST0014361

DUST SURVEY (ASBESTOS) PERSONNEL TRAINING OUTLINE

1. Develop Background
 - A. Research the Literature - Tox.
 - B. Talk with Dr. Flake - His viewpoint and Dow workers clinical evidence.
 - C. Research sample and analysis techniques.
2. Set Up Equipment In Lab - Dry Run
3. Set Up Survey at Cell Manufacturing, etc. and Get Samples
4. Have Samples Analyzed - U.S.P.H.S. Method
5. Evaluate Data and Write Technical Report

ST0014362

JAB/ks
10/27/70
S & LP