

ROTUNDA BRAKE AND CLUTCH SERVICE VACUUM

LABORATORY-TESTED AND CERTIFIED TO COMPLY WITH CURRENT O.S.H.A. REQUIREMENTS FOR ASBESTOS FIBER FILTRATION

34-8009

Special Price through December 30, 1977: \$379.00

Regular Price: \$435.00

SAVINGS OF: \$56.00

Studies by ASIA and NIOSH indicate that exposure to excessive amounts of asbestos may be hazardous to your health. O.S.H.A. has recommended procedures to reduce levels of airborne asbestos dust to which workers are exposed.

(SEE COMPLETE INFORMATION ON OVERLEAF TO LEFT.)

Rotunda's Model 34-8009 Brake and Clutch Service Vacuum has been tested by the manufacturer (Clayton Environmental Consultants, Inc.) and is certified by them to comply with these procedures for meeting O.S.H.A. requirements.

NOTE: Vacuum includes 5 Replacement Kits for a total of 5 months' service.

SPECIFICATIONS:


- Heavy-duty motor develops 2 H.P., U/L approved, 110-volt, 10-amps, 110" water lift, 115 CFM
- 10' x 1-1/2" I.D. flexible plastic hose, with connector, crevice tool and duster brush accessories.
- Steel platform chassis with two 8" rubber wheels and front caster for mobility in service areas.
- Durable chrome and epoxy finish
- Dimensions 36" H x 20" W x 24" deep with 16" diameter tank

FILTER PACK


34-0010

\$66.00

Filter contains four complete Replacement Filter Kits, providing up to four months of service. Filters must be changed monthly to maintain the required high efficiency. Each includes: Asbestos dust filtration elements, O.S.H.A. specified respirator and disposal bag.



LABORATORY-TESTED
AND CERTIFIED TO COMPLY
WITH CURRENT O.S.H.A.
REQUIREMENTS FOR ASBESTOS
FIBER FILTRATION



012191

PRODUCED BY FORD