



The Dow Chemical Company

Midland, Michigan 48674

1803 BUILDING
May 27, 1992

S. D. Barnard, 219, Indianapolis
K. J. Chicoine, Kansas City
T. S. Cox, Clifton
D. E. Cragar, B-101, Freeport
S. L. Dombrowski, 1803 Building
R. A. Dommer, 1803 Building
G. W. Engdahl, 258 Building
R. M. Hahne, 1803 Building
K. E. Heckelman, 2030 Dow Center
B. A. Houtman, DowElanco, Indianapolis
T. E. Lingafelter, DowElanco, Indianapolis
L. A. Longino, B-101, Freeport
R. W. Lutz, 1020, Sarnia
G. L. Meier, 3502E, Plaquemine
T. Parsons, 471, Pittsburg
A. F. Pollock, 2030 Building
B. W. Smith, Plymouth
R. E. Warila, 210, Indianapolis
P. R. Williams, Strongsville
W. M. Young, LaPorte

cc: File: OSHA/Welding

Sampling for Welding Fumes

In case someone might be wondering how OSHA would sample for welding fumes, here is a directive that was sent out quietly to the field offices a couple of years ago. As the directive states, the inspectors are to monitor for welding fumes inside the welding hood so they get the true employee exposure.

Dick

R. D. Olson
Regulatory Compliance
(517) 636-8295

Enc.

DO 074843
CONFIDENTIAL