

TABLE I
SUMMARY OF VCM DOSIMETRY RESULTS
MARCH 1, 1978 - MAY 31, 1978

<u>Workforce Group</u>	<u>No. Samples</u>	<u>Mean (PPM,VCM)</u>	<u>Std. Deviation (PPM,VCM)</u>	<u>2-Sigma Upper Control Unit (PPM,VCM)</u>
<u>I. Annual Schedule</u>				
1. Compound Supervisors	6	0.23	0.07	0.26
2. Dry Blend Operators	5	0.12	0.002	0.04
3. Compound Operators	4	0.10	0.00	0.10
4. Trans. Warehouse Workers	3	0.10	0.00	0.10
	<u>18</u>			
<u>II. Quarterly Schedule</u>				
1. Storeroom Supervisor	2	0.15	0.05	0.25
2. Lab Lead Techs	4	0.10	0.00	0.10
3. Lab "A" Techs	9	0.11	0.57	0.23
4. Warehouse Workers	4	0.15	0.09	0.32
5. Storekeepers	3	0.10	0.00	0.10
	<u>22</u>			
<u>III. Monthly Schedule</u>				
1. Maint. Bldg. Attendants	2	0.05	0.05	0.15
2. Maint. Util. Techs	11	0.33	0.47	1.28
3. Maint. Instr. Techs	13	0.12	0.08	0.29
4. Maint. Painters & Machinist	9	0.14	0.13	0.39
5. Maint. Electricians	10	0.09	0.03	0.15
6. Maint. Supervisors	24	0.77	2.90	6.58
7. Maint. "A" Mechanics	54	0.87	5.38	11.62
8. Maint. "B" Mechanics	8	0.19	0.27	0.73
9. Maint. Helpers	7	0.09	0.04	0.16
10. Yard Operators	13	1.69	3.26	8.20
11. Yard Supervisor	4	0.08	0.04	0.16
12. Vinyl Shift Supervisors	16	0.17	0.12	0.41
13. Vinyl LR Lead Oper.	12	0.29	0.44	1.17
14. Vinyl LR Operators	23	1.77	3.69	9.14
15. Vinyl Dryer Lead Oper.	8	0.49	1.55	1.59
16. Vinyl Dryer Util., Oper., Helpers	38	0.23	0.35	0.94
17. Process Engineers	15	0.11	0.03	0.18
18. Safety	11	0.16	0.14	0.43
19. Mechanical Engineers	22	0.12	0.10	0.31
20. Plant Mgr, Supt.	6	0.35	0.36	1.06
21. Dev. Lab. Techs.	5	0.17	0.12	0.40
22. Lab Supervisors	10	0.10	0.00	0.10
	<u>321</u>			