

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY CARD (A)

 SAMPLE NO 1315 ^A

 Hazard: VCM (X) Lead () Noise () () Date July 28-1980
 Name Douglas M. Spann S. S. # 48-66-3073 Shift A
 Department Vinyl Job Class chief operator

Instrument No. <u>416-R</u>	Time <u>6:55</u> AM() PM(<u>X</u>)	Start	Stop
Noise Cell No. _____	Airflow _____		

 Analyst: Heal Analysis Date: 8-1-80

Hazard	TWA Exposure		
VCM	PEL: 1 PPM	<u><0.1</u> PPM	
Noise	Over () Under () 115 dBA	% of PEL	
Lead (Micrograms)	TOT: PEL: Per M ³	Per M ³	

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)

 SAMPLE NO 1315 ^A

 Hazard: VCM (X) Lead () Noise () () Date July 28-1980
 Time Clock (Lead Sampling Only) : IN: _____ AM() PM() OUT: _____ AM() PM()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
<u>V. Control</u>	<u>12</u>		

List most likely causes of possible overexposure to the hazard.

- _____
- None
- _____

Check respiratory protection you used:

() None () Dust Mask () Air-line Respirator () Scott Air-pak

 Signature Rub. Hale

Please complete and return to guard