

WRG 001088



June 29, 1971

Mr. Mark Bonsignor
Eastman Kodak Company
Rochester, New York 14603

Dear Mr. Bonsignor:

I have seen the sample of mixed and dried MK-4, prepared in your lab, which shows such poor physical properties. It would appear that the sample sent to you was defective; low in gypsum content and high in vermiculite. May I assure you that our Trenton plant has been shipping several thousand bags per week of MK-4 to a number of job locations and our field troubles have been minimal. We are truly embarrassed to have furnished you with material that is not representative.

Subsequent to our phone conversation, I discovered that our Monokote Product Manager, Thomas P. Feit, has a combined travel and vacation schedule that might occasion too much delay in his availability to discuss the technical aspects of MK-4 Fire Proofing Performance with your Engineering Department. I am requesting Mr. J. Cintani, our regional Sales Manager in Trenton, New Jersey, to follow up on this and make arrangements to present our data to your company.

Robert C. Ericson
Quality Assurance
Manager

RCE/cac

cc: Fred Wertz / 4831 Carey Drive, Manlius, New York
J. Cintani / Trenton, New Jersey

bcc: W. K. Rogers /
B. Williams
P. R. Reyer / Weedsport
T. P. Feit

25115675

Attachments