



E. I. DU PONT DE NEMOURS & COMPANY
INCORPORATED

S. Red

CIRCLEVILLE



FILM DEPARTMENT

Circleville, Ohio
December 7, 1966

C. A. D'Alonzo, M. D.
Medical Director
Medical Division
Wilmington

The followin are answers to your inquiry concerning the use of asbestos at our plant.

- A. Fourteen (14) outside contractors do the major portion of our plant insulating work.
- B. An average of about one (1) plant employee per week does insulating work.
- C. The three most prevalent types of insulating material used are calcium silicate, fiberglass, and urethane foam.
- D. There is no spraying of insulation done at this plant.
- E. We have experienced none of the conditions listed.
- F. Preventive measures
 - (a) sawing insulating materials -- respirator if dust present in the shop sawing, none in the field.
 - (b) removing obsolete insulation -- face shield.
 - (c) spraying insulating materials -- not done.

Ray Carroll, M. D.
Medical Section

Dorothy G. Walsh, R.N.
By: Dorothy G. Walsh, R. N.

:dgw

DUP 1110088