


Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: June 6, 2024 11:31 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7966494510045, -70.993552325299

Photos:



Description: Hump to keep water in and prevent water coming from road


Photo ID: 1

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 11:30 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7971761455252, -70.99298023609

Photos:



Description: Site


Photo ID: 2

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 11:26 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7980338434145, -70.992901010857

Photos:



Description: Low spot


Photo ID: 3

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: June 6, 2024 11:26 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7980133398871, -70.9929239221985

Photos:



Description: Mounds


Photo ID: 4

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 11:23 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7988087984642, -70.9923436080546

Photos:



Description: General area will be a swale


Photo ID: 5

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 11:21 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7986353594766, -70.991645521015

Photos:



Description: Mulch control


Photo ID: 6

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 11:20 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7982685835839, -70.9914764576485

Photos:



Description: Screening the loam


Photo ID: 7

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 11:20 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7980993800696, -70.9914553477185

Photos:



Description: Perimeter


Photo ID: 8

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 11:18 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7972752789831, -70.992151706308

Photos:



Description: Control


Photo ID: 9

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 11:17 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7972548398665, -70.9925635917497


Photos:



Photo ID: 10



Photo ID: 11




Description: Detention basin with spillway

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 11:15 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7965217287824, -70.9930804722868

Photos:



Description: Seeded slope


Photo ID: 13

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 11:12 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7966635607837, -70.9931978136711

Photos:



Description: Sign noi


Photo ID: 14

Field Photo Report

Submitted By:

Submitted Time: June 6, 2024 11:11 AM

Project: Pauline's Path Subdivision, Lakeville, MA



Location: 41.7968505741444, -70.9932975564819

Photos:



Description: Future house

Photo ID: 15