

CONTINUOUS MONITORING LOG SHEET

CONFIDENTIAL

Location Process Air-2

Date 2/10/79

NAME																									
TIME	Stream No.	0700	0800	0900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000	2100	2200	2300	2400	0100	0200	0300	0400	0500	0600
1		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
2		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
3		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
4		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
5		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
6		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
7		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
8		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
9		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
10		/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/	/
	Flame On																								
	Plant Air On																								

Comments:

VCM Tank Farm

- 1 South Unloading Station
- 2 Middle Unloading Station
- 3 North Unloading Station
- 4 Compressor Shed
- 5 Process Control Room
- 6 VCM Storage Tanks - 201 & 202
- 7 Respirator Air Inlet
- 8 Dryer Line #6, Blend Tanks, 1st Floor
- 9 Dryer Line #6, Activator, 1st Floor
- 10 Spare

DTH 000083711