

CITATION

C-1645	97
WCA	WCA
Pgh.	3



TO: 2. Foseco-Minsep, Incorporated
Mt. Braddock Plant
Mt. Braddock, Pennsylvania 15465

3. Citation Number 1
4. Page 1 of 5. 2

6. TYPE OF ALLEGED VIOLATION(S): NONSERIOUS

An inspection was made on 9/2 to 11/13 19 75 of a place of employment located at:

8. Mt. Braddock Road, Mt. Braddock, Pennsylvania and described as follows:

9. Manufacture of hot toppings for steel mills

On the basis of the inspection it is alleged that you have violated the Occupational Safety and Health Act of 1970 29 U.S.C. 651 et seq., in the following respects:

10. Item number	11. Standard, regulation or section of the Act allegedly violated	12. Description of alleged violation	13. Date by which alleged violation must be corrected
1	29CFR 1910.1000 formerly 29CFR 1910.93	Employee(s), in the following location(s), were exposed to material(s) listed in Table(s) 2-3, _____ of this section, and their exposures were not limited in accordance with the requirements of 29CFR 1910.1000(c), (), (). Samples were obtained at the breathing zone of the employee(s): (a) Pre-mix area (b) Cement-mixing area (c) Pulper Employee(s) at the preceding locations (a) to (c) inclusive, were exposed to respirable quartz in excess of eight-hour time weighted average.	December 1976
2	29CFR 1910.1001 (g)(1)(i) formerly 29CFR 1910.93a (g)(1)(i)	Caution signs, advising employee(s) of the asbestos dust hazards, were not posted at all approaches to the following area(s), where airborne concentrations of asbestos fibers may have been in excess of the exposure limits prescribed in paragraph (b) of this section: (a) Pro-call building	December 1975
3	29CFR 1910.1001 (g)(2)(i) formerly 29CFR 1910.93a (g)(2)(i)	Caution labels were not affixed to asbestos containing materials or their containers, at the following locations, in accordance with the provisions of this section: (a) Pro-Cal Building	December 1975

FOSECO 1782

FOS-02-0000002569