

**CONOCO CHEMICALS – ABERDEEN PVC PLANT
DOSIMETRY CARD (A)**

SAMPLE No 1772

 Hazard: VCM (☒) Lead () Noise () () Date 11/1/80

Name Doug Spann S. S. # 411/14/3072 Shift A (F)

Department Vinyl Job Class Chief Lead

Instrument No. 294	Start Time 6:37 AM () PM (X)	Stop Time 7:02 AM (X) PM ()
Noise Cell No. _____	Airflow _____	

Analyst: J. Grace Analysis Date: 11-12-80

Hazard		TWA Exposure
VCM	PEL: 1 PPM	0.3 PPM
Noise	Over () Under () 115 dBA	% of PEL
Lead (Micrograms)	TOT: PEL: Per M ³	Per M ³

**CONOCO CHEMICALS – ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)**

SAMPLE No 1772

 Hazard: VCM (☒) Lead () Noise () () Date 11/1/80

Time Clock (Lead Sampling Only) : IN: _____ AM () PM () OUT: _____ AM () PM ()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
Dryers	4		
Rx's	4 1/2		

List most likely causes of possible overexposure to the hazard.

1. Recovery Systems
2. _____
3. _____

Check respiratory protection you used:

☒ None () Dust Mask () Air-line Respirator () Scott Air-pak

Signature Doug Spann

Please complete and return to guard