

January 11, 1980

nine rating and no problems experienced. It is noted that the pedal force to decel might be a little high compared with production and the skid checks might also be a little high.

There are not substantial enough complaints to get the material off the vehicle. A copy of their brake evaluations is attached to the various copies of this report.

Earle

L. Earle Bretz, Jr.

LEB/sw
Attachment

cc: AFSchmaltz/file
RENelson
ADIndelicato
VGarthwaite
JVanMarcke
BJIwarsson