

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	03/31/2021	
Media Program:	Water	
Regulatory Program(s)	CWA – NPDES, Produced Water	
Company Name:	McCann Resources, Inc.	
Facility Name:	Hulah Lake	
Facility Physical Location:	36.917940, -96.115215	
(city, state, zip code)	Bowring, Oklahoma	
Mailing address:	1613 W 6 th St.	
(city, state, zip code)	Bartlesville, Oklahoma 74003	
County/Parish:	Osage County	
Facility Phone Number	918-337-4747	
Facility Contact:	Mark McCann	
FRS Number:	N/A	
Identification/Permit Number:	OKU000895	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Kent Sanborn	EPA, 6ECDW	EPA Lead Inspector
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		19 APR 2021
	Guy Tidmore	Date

Section I – INTRODUCTION

Purpose of inspection

EPA Region 6 inspector Kent Sanborn arrived at the McCann Resources, Inc. Hulah Lake facility at 10:00 am on 03/31/2021 for an inspection of a lease that reportedly had an oil and brine spill. There were no facility representatives present at the site. The inspection was conducted under the authority of the Clean Water Act (CWA) to assess a previously reported spill from a producing oil well. The scope of the inspection is to assess unauthorized discharges and impacts of nearby water resources under the CWA.

Facility Description

The facility was a producing well identified as well 1A in SW 10-28N-11E (Osage County, Oklahoma).

Section II – OBSERVATIONS

I had the following observations during the inspection:

The producing well had leaked from a line a short distance to the lease road. The spill did not enter the lake or a flowing stream. Some oil staining in the leaves but pools of remaining fluids only measured 380-1,500 milligrams per liter (mg/L) Total Dissolved Solids (TDS). All measurements were taken with a successfully calibrated YSI conductivity meter. The flow line had been repaired.

Were control measures put in place?	Yes
National Response Center (NRC) notified?	Yes
Remedial action ongoing?	Yes
Downstream Observations?	N/A
Upstream Observations?	N/A
Spill Ongoing?	No
Spill reached waterbody?	No
Aquatic Life Kill/Damage?	N/A
Vegetation damage?	N/A

Section III – AREAS OF CONCERN

The following areas of concern were identified:

- Some elevated fluids above background were observed on surface

Section IV – FOLLOW UP

The following follow up actions that are recommended for EPA are:

- None

Section V – RESOURCES

Below are compliance resources for oil and gas facilities:

- To report spills associated with your facility, call: **1-800-424-8802**, for more information: <https://www.epa.gov/pesticide-incidents/how-report-spills-and-environmental-violations>.
- For information regarding Spill Prevention, Control, and Countermeasure (SPCC) program: <https://www.epa.gov/oil-spills-prevention-and-preparedness-regulations/facility-owneroperators-guide-oil-pollution>.
- For information regarding Underground Injection Control (UIC) (Safe Drinking Water Act): <https://www.epa.gov/uic>.