

C3 123
44675019

Choppers

Hand feel
rather than drop

Don't
want to
no car
by the
not its people

Don't know up room. Fall
Don't collect on up table Doc -
anyone would not make

ENGINEERING REPORT

GENUINE PARTS COMPANY
RAYLOCK DIVISION
100 Raylock Drive
Hancock, MD 21750

prepared by

• DAVID W. GLASSMAN
Loss Control Engineer
Industrial Hygiene and
Environmental Service Unit

January 16, 1991


TheTravelers

• Industrial Hygiene
Evaluation

THE TRAVELERS
ENGINEERING DIVISION

Engineering Services Protecting People and Property Since 1894

C 17162 1 R683 Printed in U.S.A.



NAPA 039

NOVO20415

SCF-NAPA-4500